

Isolating Connectors

700PARTD1_

1.6





SPECIAL INSTALLATIONS

GENERAL PRODUCT INFORMATION:




This product is suitable for indoor dry locations only.

This product is intended to be used with Tech Lighting Kable Lite system only.



1 Loosen (Do Not Remove) the six #4-40 set screws with the provided 0.05 Allen wrench to clear the side holes.



2 Feed end of one Kable Lite cable half way into the side hole of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.

3 Feed the other Kable Lite cable half way into the other end of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.

4 Repeat steps 1 through 3 for the other isolating connector.

SAVE THESE INSTRUCTIONS!



7400 Linder Ave, Skokie, IL 60077
847.410.4400

www.techlighting.com

© 2008 Tech Lighting, L.L.C. All rights reserved. The "Tech Lighting" graphic is a registered trademark of Tech Lighting, L.L.C. Tech Lighting reserves the right to change specifications for product improvements without notification.
A Generation Brands Company