

# INSTRUCTIONS DRY FINISH FOR BRONZE

- SOFT CLEANING CLOTH
- WEIMAN WIPES OR OLD ENGLISH OIL



1. If using Old English, apply a generous amount of English oil to your affected area using a dry soft cloth OR use Weiman Wipes to rub evenly over the dry, affected areas. Continue until there is a nice, even coating of product.
2. Turn the cloth over to a dry side and lightly polish over the area to remove excess product.
3. If needed repeat steps 2 through 3 until the affected areas look oil rubbed to satisfaction.

TIP: Although this is intended to remedy a dry area of the item, this process is an excellent way to keep your item looking great.

















