

ATTENTION! Prior to installation, the following connection must be made at the inlet of the Secondary Deionization filter:




FIG 1. Plugs Removed



FIG 2. Fitting & Clip Installed