


PTB021SL

METAL CHICKEN COOP



IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL



1 x 4
1320



2 x 14
1825



2A x 4
1825



3 x 16
970



3A x 4
970



5 x 2
1882



5A x 1
1882



6 x 1
605



Φ16 395mm

10 x 8
395



A x 2
1700




B x 1
1845



C x 2
497



P x 1
1.92x3.47m



Q x 1
45m

D × 8



E1 × 2



E2 × 2



F × 5



G × 1



H × 8



I × 26



J × 2



K × 31

M6
+2(spare)




L × 4


M8
+1(spare)



M × 1



O × 2



R × 12



S × 1






W × 10











ATTENTION: E1 & E2 shall be placed in strict order, otherwise they cannot be installed

DIFFERENT HOLES SITUATIONS IN E1&E2


















07



08





P



R

