


## 93+ Supra 1-Piece CV Driveshaft

Not checking this will void the warranty:



Driveshaft CV Clearance MUST BE CHECKED after installation.  
1993-1998 Supra (Auto / Manual) must be between 3.25" – 3.75"  
If dimension is not within the allowed range, do not run the driveshaft

Adapter plate Hardware Torque:

Front: (4) 7/16" Bolts 70 ft-lbs / (4) M10 Bolts 57 ft-lbs  
Rear: (3) 7/16" Bolts 70 ft-lbs / (4) 3/8 Bolts 54 ft-lbs