Re) LOAD AND USE YOUR NEW OYNG PLUCE

FIRST: ROLL PLUG BETWEEN YOUR THUMB AND FOREFINGER TO NARROW ITS DIAMETER BEFORE LOADING. ** DO NOT HOLD BRASS TIP WHILE ROLLING

Second: Slide Plug ONNA: PLUG! INTO INSERTION TUBE
UNTIL BRASS TIP IS FLUSH AGAINST THE TUBE

*IF PLUG IS TOO STICKY OR WON'T FIT IN THE TUBE,

RE-ROLL & APPLY SOME SALIVA/WATER TO LUBE THE PLUG. YOU CAN

ALSO CLEAN THE TUBE WITH A PIPE CLEANER + RUBBING ALCOHOL.

REPAIRING A PUNCTURE ->> BACK TO SHREDDING

TIPS AND TRICKS
• SOMETIMES IT TAKES
MULTIPLE PLUGS TO SEAL
A GNARLY PUNCTURE.
• AFTER YOU PLUG, SPIN
YOUR WHEEL TO SPREAD
THE SEALANT AROUND.

STEP L.


FIND THE PUNCTURE A

LISTEN FOR

THE HISSSS...

* use your free hand to Keep air from escaping. STEP 2

ALIGN TOOL WITH THE PUNCTURE



STEP 3

PUSH TOOL ALL


THE WAY (
THROUGH
PUNCTURE



STEP 4:

PULL TOOL FROM PUNCTURE

PLUG WILL



X IF Needed

MADE IN CHICO CA! PATENT# 8,707,829 * 2021



