HOW TO: Dynaplus (Re) LOAD AND USE YOUR NEW RACER PRO

FIRST: ROLL PLUG BETWEEN YOUR THUMB AND FOREFINGER TO NARROW ITS DIAMETER BEFORE LOADING. ** DO NOT HOLD BRASS TIP WHILE ROLLING



Second: SLIDE PLUGINTO INSERTION TUBE

UNTIL BRASS TIP IS FLUSH AGAINST THE TUBE

* IF PLUG IS TOO STICKY OR WON'T FIT IN THE TUBE,

RE-ROLL & APPLY SOME SALIVA/WATER TO LUBE THE PLUG. YOU CAN

ALSO CLEAN THE TUBE WITH A PIPE CLEANER + RUBBING ALCOHOL.

REPAIRING A PUNCTURE ->> BACK TO SHREDDING

TIPS AND TRICKS
• SOMETIMES IT TAKES
MULTIPLE PLUGS TO SEAL
A GNARLY PUNCTURE.
• AFTER YOU PLUG, SPIN
YOUR WHEEL TO SPREAD
THE SEALANT AROUND.

STEP I. FIND THE PUNCTURE WAR


LISTEN FOR THE HISSSS.

* use your free hand to Keep air from escaping.

STEP 2

INSERTIONTUBE

ALIGN TOOL WITH THE PUNCTURE



STEP3:

THE WAY
THROUGH
PUNCTURE

STEP4:

PULL TOOL FROM PUNCTURE.
PLUG WILL

REMAIN IN THETIRE. ONCE LEAK STOPS, TRIM PLUG, & ADD AIR.

* IF Needed

MADE IN CHICO CA! PATENT# 8,707,829 * 2021



