




Shadow Vision 20" Instructions

If you prefer to use a connector of your choice, you may cut the DT connector off. This does not affect the warranty. Please make sure you remember the cable positions before making the cut so that you know which cable has which function.

PARTS INCLUDED


- A. 2x Universal side mounting bracket
- B. 2x M8 stainless steel bolts
 - 2x M8 Allen bolts
 - 2x M8 spring washers
 - 2x M8 nuts
- C. 4 PIN DT Deutsch connector (male)



TOOLS REQUIRED

- Allen key
- Wrench 13 mm

DT Connector



DT Connector wiring position

DT Cable Position	Cable Function	Cable Colour
1	Grounding (Negative -)	Black
2	White position light (10-30V DC +)	White
3	Amber Position light (10-30V DC +)	Yellow
4	Driving beam (10-30V DC +)	Red

How to choose between E-mode and off-road mode

This light bar is equipped with both a reduced E-mode and a full blast off-road mode. Follow these steps to switch between the two intensities:

- Step 1: make sure that the driving beam is turned off for at least 5 seconds.
- Step 2: Turn on the driving beam for 2 seconds, turn it off and immediately turn it on and off 3 times briefly and quickly
- Repeating these two steps will switch between the E-mode and off-road mode