spirax sarco

TI-P163-01

ST Issue 8

Fig 12 SG Iron Strainer

Description

The Fig 12 is an SG iron screwed Y-type strainer. The standard stainless steel screen is 0.8 mm perforations. As options, other perforations and mesh sizes are available as well as monel screens. The strainer cap can be drilled and tapped for blowdown and drain valves if required.

Standards

This product fully complies with the requirements of the European Pressure Equipment Directive 97/23/EC.

Certification

This product is available with a manufacturers' Typical Test Report. **Note:** All certification/inspection requirements must be stated at the time of order placement.

Sizes and pipe connections

1/2", 3/4", 1", 11/4", 11/2", 2", 21/2" and 3" screwed BSP or NPT.

Optional extras

Strainer screens


Stainless steel screen	Perforations	1.6, 3 mm	
Stailliess steel screen	Mesh	40, 100, 200	
Monel	Perforations	0.8, 3 mm	
Monei	Mesh	100	

Blowdown or drain valve connections.

The cap can be drilled to the following sizes to enable a blowdown or drain valve to be fitted.


Strainer size	Blowdown valve	Drain valve	
1/2"	1/4"	1/4"	
3/4" and 1"	1/2"	1/2"	
11/4" and 11/2"	1"	3/4"	
2" to 3"	11/4"	3/4"	


Pressure/temperature limits



The product **must not** be used in this region.

Body d	esign conditions		PN25				
PMA	Maximum allowable pressure	25 l	oar g @ 120°C				
TMA	Maximum allowable temperatur	e260°C @ 19	9.5 bar g				
Minimu	m allowable temperature		-10°C				
РМО	21 bar g						
TMO	TMO Maximum operating temperature 260°C @ 19.5 bar g						
Minimu	m operating temperature	½" to 2"	-10°C				
2½" and 3"							
Note: For lower operating temperatures consult Spirax Sarco							
Design	Designed for a maximum cold hydraulic test pressure of 38 bar g						





Materials


No.	Part	Material	
1	Body	SG iron	DIN 1693 GGG 40
2	Сар	Carbon steel	1.0460 and ASTM A105N
3	Cap gasket	Reinforced exf	oliated graphite
4	Strainer screen	Stainless steel	316L
5	Bolt	Carbon steel	BS 3692 Gr. 8.8
6	Washer	Carbon steel	BS 4320 TI Form A

spirax /sarco

K _V values				For conversion:	$C_V(UK) = K_V \times 0.963$		C _V (US) = K _V x 1.156	
Size	1/2"	3/4"	1"	11/4"	11/2"	2"	21/2"	3"
Perforations 0.8, 1.6 and 3 mm	3.6	11	15.5	26	41	68	82	115
Mesh 40 and 100	3.6	11	15.5	26	41	68	82	115
Mesh 200	3.6	9	13.0	21	35	55	66	93

Dimensions/weights (approximate) in mm and kg

					Screening	
Size	Α	В	С	D	area cm²	Weight
1/2"	87	55	79	32	25	0.47
3/4"	110	65	93	36	42	0.77
1"	125	78	110	48	71	1.40
11/4"	155	103	140	60	135	2.15
11/2"	190	115	153	65	161	3.30
2"	230	140	177	76	251	5.10
21/2"	274	177	230	94	406	7.30
3"	280	183	237	105	406	7.50



Safety information, installation and maintenance

For full details see the Installation and Maintenance Instructions (IM-S60-17) supplied with the product.

Warning:

The strainer cap gasket contains a thin stainless steel support ring, which may cause physical injury if it is not handled and disposed of carefully.

Installation note:

The strainer should be installed in the direction of flow, as indicated on the body. On applications involving steam or gases the pocket should be in the horizontal plane. On liquid systems the pocket should point downwards. Suitable isolation valves must be installed to allow for safe maintenance and trap replacement.

Maintenance note:

Maintenance can be completed with the strainer in the pipeline.

Disposal:

The product is recyclable. No ecological hazard is anticipated with disposal of this product providing due care is taken.

How to order

Example: 1 off Spirax Sarco 2" Fig 12 SG iron strainer, screwed BSP, with stainless steel screen having 0.8 mm perforations.

Spare parts

The spare parts available are shown in solid outline. Parts drawn in broken line are not supplied as spares.


Available spares

Strainer screen	4
(state material, size of perforations or mesh and size of strainer)
Cap gasket (packet of 3)	3

How to order spares

Always order spares by using the description given in the column headed 'Available spares' and state the size and type of strainer and perforation or mesh required.

Example: 1 - Strainer screen, stainless steel having 0.8 mm perforations for a 1½" Spirax Sarco Fig 12 strainer.



Recommended tightening torques

Recommended agricuming torques							
Item	Qty	Size		or mm	*	N m	
2	1 1 1 1 1	1/2" 3/4" 1" 11/4" 11/2" 2"	36 38 50 46 50 60		M28 M32 M42 M56 M60 M72	38 - 40 42 - 48 70 - 80 124 - 144 164 - 184 234 - 264	
5	4 4	2½" 3"	19 19		M12 M12	50 - 55 50 - 55	