

Vent Free appliances can only be installed in some areas of the United States.

FVF350 VENT FREE FREE STANDING GAS STOVE





Vent Free appliances can only be installed in some areas of the United States.

MVP

2340 Logan Avenue Winnipeg, Manitoba, Canada R2R 2V3 Phone: (204) 632-1962 Fax: (204) 632-1960 www.kingsmanfireplaces.com

Model	FVFB350MVN	FVFB350MV
Input Low	25,000 BTU	27,000 BTU
Input High	40,000 BTU	37,000 BTU
Valve Type	Millivolt	Millivolt
Efficiency	99.9%	99.9%

The ultimate in Vent-Free Free Standing Gas Stoves for new home construction or renovation, and your best choice for installation anywhere throughout your home.

STANDARD FEATURES

- Millivolt Valve with Hi-Low heat and flame adjustment . and allows operation during a power failure
- Dual burner system, with realistic flame pattern
- Black Arch Door with Fixed Mesh Screen*
- Equipped with 100% safety shut-off feature (ODS) Oxygen Depletion Sensor
- Black Louver .
- Fibre Oak Log Set*
- No chimney or vent required, maximizes location flexibility
- Safety Screen Barrier

OPTIONAL FEATURES

Fan Kit

Heat activated blower with variable speed control

Thermostat


Wall Mount Millivolt Thermostat or Programmable Thermostat


Remote Control

On/Off, Thermostat On/Off, Thermostat On/Off modulating

Brick Refractory Liner

3 pieces





30 ³/8"

27 5/16

19 ¹/₁₆"

19 ¹/₁₆"

А





Traditional Brick Liner





MINIMUM CLEARANCES TO COMBUSTIBLES

- 12" from side of unit
- 3" from back of unit
- 3″ from side of unit in corner
- 41" from top of unit

 (\mathbf{I})



ZI Z21.11.26-1998 for the FVF350 V

ts may have to be ordered separately to create a com

Printed in Canada 09/2020 - B031

plete unit. Discuss with your local Kingsman dealer for clarificatior

FOR CALIFORNIA RESIDENTS ONLY:

WARNING! This product can expose you to chemicals including Carbon Monoxide, that is an externally vented by-product of fuel consumption, which is [are] known to the State of California to cause birth defects or other reproductive harm. For more information, visit www.P65Warnings.ca.gov.