

**MULTI-SURFACE
CERAMIC
CLEARCOAT
PURE AIR COATING**

You will need:

- Hot water pressure washer
- Fan tip on wand
- Battery leaf blower
- Chemical tank or backpack sprayer
- SIMIX Multi-Surface Cleaner & Degreaser**
- SIMIX Multi-Surface Ceramic Clearcoat**
- Distilled or RO water (for coating)

Clean & Coat Asphalt Shingle and Barrel Tile Rooftops

INSTRUCTIONS

Clean with **SIMIX Multi-Surface Peroxide Cleaner & Degreaser**

Step 1: Clean debris off roof with pressure washer or leaf blower.

Step 2: Dissolve **SIMIX Multi-Surface Peroxide Cleaner & Degreaser** in hot water. Use 1 large scoop of powder per gallon of water. In Chemical tank make sure solution sprayed on roof is 4 ounces per gallon or equivalent.

Step 3: Immediately apply the solution. Rooftop should be completely soaked.

Step 4: Allow to dwell for 20 minutes.

Step 5: Rinse off with pressure washer. Repeat if needed until roof is visibly clean.

Step 6: Let roof visibly dry before applying **SIMIX Multi-Surface Ceramic Clearcoat**.

Coat the Roof

Prepare **SIMIX Multi-Surface Ceramic Clearcoat**. Refer to **Mixing/Dilution chart** (sheet).
Check temperature and consult mixing chart for proper amounts.

Step 1: Spray coating on to dry roof.

Step 2: Let coating visibly dry.

Step 3: Add 3 more coats. Always let coating visibly dry between coats.

| Roofs surfaces | Asphalt Shingle, Barrel Tile (minimum 4 coats) | | |
|--------------------------------|---|--------------------------------|--|
| Surface Temperature | 45° - 99°F | 100° - 120°F (40% humidity) | 100° - 120°F (less than 35% humidity) |
| SIMIX | 1 Part | 1 Part | 1 Part |
| Distilled or RO water | 6 Parts | 9 Parts | 14 Parts |
| Coverage/per mixed gal. | 600 -1200 sq. ft. | 500 -1000 sq. ft. | 400 - 800 sq. ft. |

Coverage rates will vary based on type of surface, porosity, ambient temperature, surface temperature and humidity.

