Assembly instructions

Trace

Please note

Please read these instructions carefully and keep them for future reference. Refer to the parts inventory and ensure you have all the parts before starting. During assembly, place all parts on a flat, soft and clean surface, such as a carpet or blanket, to prevent scratches and damage. We recommend that a minimum of two people help each other to assemble.

Parts inventory


A Legs

B Socket head screws

C Allen key

Assembly

Attach the legs (A) by inserting the socket head screws (B) into the predrilled holes, securing them with the Allen key (C).







Mosevej 20A DK-8240 Risskov wmd@wendelbo.dk +45 87 400 800 wendelbo.dk @wendelbodk