
Alys

BEDS

Gabriele and Oscar Buratti



Description

A sheet of leather “pinched” in two places at the base: here is where the movement and natural inclination of the Alys headboard originate. The Buratti brothers are once again managing a material that they know well because they’ve already used it on the Doyl chair when they explored the theme of upholstered leather, made more comfortable than with traditional processes. For Alys, they designed a comfortable, protective headboard, a very effective shape that has thin perimeter strips marked by a lengthwise seam. The bed frame can be placed at two different heights, thanks to a standard equipment made of two sets of feet (h. 5cm or 15cm). The bed surface was designed to be low specifically to suggest an effect of suspension and floating of the super-comfortable mattress.

Technical information

Internal frame:

tubular steel and steel profiles

Internal frame upholstery:

Bayfit® (Bayer®) flexible cold shaped polyurethane foam, polyester fibre cover

Bed sides:

anodized aluminium extrusions

Feet:

black thermoplastic material

Slatted base:

tubular steel and beechwood multilayer slats


Support crosspieces for slatted base:

painted tubular steel


Cover:

natural, black, dark brown, tortora, ivory thick leather or natural, black, dark brown, bordeaux, bottle green, mud green embossed thick leather


Technical drawings




LY160




LY170




LY180




LY200




LY153




LY193




210LY160



210LY170



210LY180



210LY200

B&B Italia reserves the right to make technological and aesthetic improvements to its models, including changes to the sizes and materials, without notice. The technical drawings do not define the details of the product. The measurements shown are indicative and may undergo changes. In particular, the dimensions relevant to the padded parts are subject to usage tolerances over time caused by the normal adjustment of the padding. For the specific information, please contact the dealer closest to you.