

# **Gruissan • RAHSL60B3**

# 60cm Canopy Range Hood



# Signature Features

## **High Performance**

 Powerful air extraction of up to 300m3/h and enhanced by a 3-speed fan mode, you can boil, simmer and stir-fry.

## **Gesture Control Technology**

• Wave on and wave off to keep your kitchen odor free from fumes. Conveniently control your rangehood even when your hands are wet or dirty.

### **Head Free Design**

· Sleek and ergonomic design, giving your kitchen a modern touch and an optimal view of your cooktop.

### **Optimal Clean Air**

• Equipped with double activated charcoal filter and a 5-layer filter for optimal smoke and odor absorption capacity.

## **Eco Friendly LED Lights**

• Environmentally responsible LED light (1.5 W) provide ample clarity over the cooking area

#### **Intuitive Touch Control**

• Easy to understand and easy to operate, so you can easily adjust the power and access all of the important functions at your fingertips































# **Gruissan • RAHSL60B3**

# 60cm Canopy Range Hood

# **Technical Features**

Materials / Color: Stainless steel Installation: Wall-mounted 220-240V, 50Hz Voltage / Frequency: Current: 0.3

# **Range Hood Features**

Power Levels: 3 Speeds Motion Sense Technology: Yes Yes Adjustable Length: **Electronic Control** Control Display: Max. Air Extraction Power: 300m3/h 65W Motor Power: 1.5W Rated Lamp Power (each): LED Lights: Sound Power Level: 65db Indicators / Display: Fault indicator

#### **Filter Features**

Aluminum/Stainless Steel Surface Filter: 5 layers Activated Charcoal Filter (CF130): Yes (2 pieces)

# **Dimensions & Weight**


Packed dimensions: 66 (W) x 41 (D) x 44 (H) cm Packed weight: 11.2kg 60 (W) x 33.3 (D) x 64.3-92.3 (H) cm Unpacked dimensions: Unpacked weight: 9.6kg


## Warranty

Two (2) year parts and labor

\*Extend your warranty by registering your product linarie.com.au

# **Installation Drawings**





Please refer to the user manual for detailed installation and for filter replacement instructions. Insufficient distance between the cooktop and the rangehood can result in damage to the rangehood.



@Linarie.Appliances