4cm



WARNING: THE FAILURE TO FOLLOW THESE INSTRUCTIONS WHEN INSTALLING THE LEDRURLZ 194 -MULTICOLOR MAY CAUSE ELECTRIC PROBLEMS IN YOUR VEHICLE WHICH COULD CAUSE VEHICLE DAMAGE FLECTRICAL SYSTEM DAMAGE, FIRE. ELECTRICAL SHOCK. PERSONAL INJURY OR DEATH.

WARNING: DO NOT LOOK DIRECTLY INTO THE LEDRURY 7 194 MULTICOLOR. DO NOT DRIVE POSITION YOUR VEHICLE NEA ONCOMING TRAFFIC WHEN THE I FORURI 7 194 - MIII TICOLOR I POWERED ON - DOING SO MAY

RESULT IN VISION IMPAIRMENT AND OR VEHICULAR COLLISION. THE INTENDED USE OF THE LEDRURY - MIII TICOLOR IS TO PROVIDE INTERIOR & EXTERIOR ACCENT LIGHTING FOR OFF ROAD LISE ONLY THIS PRODUCT IS NOT DOT

INSTALLATION GUIDELINE WARNING: SAFETY GLASSES

MUST BE USED WHEN INSTALLING THIS PRODUCT. LEDBULBZ 194 - Multicolor is a bulb light driver or other drivers

designed to provide interior auxiliary and accent lighting while driving off road. FDBULB7 194 - Multicolor has a dis amperage draw below in the installainstructions. If you are not confident in your ability to install the LEDBULBZ 194 Multicolor please consult a licensed

194 input and amperage draw, ENSURE THESE RATINGS ARE FOLLOWED. LEDBUL B7 194 - Multicolor must be installed in the correct socket size (specified on the package) and in a properly functioning vehicle electrical system. DO NOT install this product in

electrical system

These lights should not be installed where

WARNING: DURING OPERATIO LIGHTING UNITS CAN GET HOT - DO NOT TOUCH WHILE OPERATIONAL WITHIN 30 MINUTES OF POWERING

this equipment does cause harmful Before disconnecting battery terminal interference to radio or television

FDRUI R7 194 - Multicolor has specific voltage and amperage ratings for power anything other than the specified socket types or in a malfunctioning vehicle

These limits are designed to provide reasonable protection against harmfu their operation hinders the visibility of the

iterference to radio communications There is no guarantee that interference

nlease check your owner's manual t

Federal Communications Commission (FCC) Interference Statement

nis equipment has been tested and found to comply with the limits for a B digital device, pursuant to Part 15

> Consult the dealer or an experienced radio/TV technician for help.

FCC Rules. Operation is subject to the stalled and used in accordance with the

 This device may not cause harmful interference, and (2) this device must accept any interference received including interference that may cause will not occur in a particular installation. If

FCC Caution: Any changes or reception, which can be determined by modifications not expressly approved by turning the equipment off and on, the user is encouraged to try to correct t the party responsible for compliance interference by one of the following could void the user's authority to operate

 Reorient or relocate the receiving RF exposure warning

 Increase the separation between the is equipment complies with F radiation exposure limits set forth for ar

a circuit different from that to which the The equipment must not be co-located or receiver is connected operating in conjunction with any other antenna or transmitter

WARNING: Cancer and Reproductive Harm

www.P65Warnings.ca.gov

may not apply to you

NO INCIDENTAL. CONSEQUENTIAL OR

ALPENA® LIMITED WARRANTY

materials or workmanship of this produ for one (1) year from the date of purchase. Normal wear and tear over time are not product defects. Product problems caused by not following the product instructions, abuse, misuse, alteration, accident and/or use beyond the product's intended purpose are no covered. This warranty is valid for the original owner and is not transferable. Proof of purchase is required

Any implied warranties and conditions such as merchantability and fitness for particular purpose are hereby excluded or if not excludable under law are limited to one (1) year period. Some jurisdiction do not allow limitations on how long ar implied warranty lasts, so this limitation

SPECIAL DAMAGES ARE RECOVERABLE SOME JURISDICTIONS DO NOT ALLOW

THE EXCLUSION OF INCIDENTAL CONSEQUENTIAL OR SPECIAL DAMAGES SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU. THIS WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS AND YOU MAY HAVE OTHER RIGHTS WHICH VARY DEPENDING ON THE JURISDICTION.

> product return directions. Please note that replacement product may not be exact due to style changes to our products. We will cover the mailing expense to send you a replacement available at the time you submit your warranty request, we will issue a credit.

to be defective provided you follow our

Marklyn Group Inc. 753011 2nd line EHS Mono, ON, Canada L9W 5W4 Alnena® is a registered trademark of Marklyn Group Inc. © Copyright 2023 Made in China

product. However, mailing costs to return to us the original product which is claimed to be defective must be paid by you. If a replacement product is not

@AlpenaAutomotive 1-800-387-3217

For warranty service, please see below.

NORTH AMERICAN SUPPORT AVAILABLE

0 A D L

NOTE: IF BULB DOESN'T WORK AFTER

1. INSTALLATION

Ensure vehicle power is turned off and bulb to be replaced is off

Remove bulb cover or housing

equired to access the light bulb that

3) Remove existing bulb using gloves.

) Test operation by turning on the

lower, if light does not turn on ren

Replace cover or re install housing

INSTALL REMOVE AND ROTATE THE BULB

wish to replace

REINSTALL AFTER ROTATING THE BULE

Replacement remote battery is 3V, CR2025

Flashing all colours

2. OPERATION



DISTRIBUTED BY WEBER LOGISTICS 14909 SUMMIT DRIVE EASTVALF CA 92880 I P: 909.378.2011

F: 909.378.2099

WWW WERERI OGISTICS COM