

Anti Cash-Trapping cleats for SelfServ 6626



SelfServ 6626

There has been a recent cash trapping attack on the SelfServ 6626 ATMs. A metal cover is fitted in front of the shutter. A solution to prevent this attack is the Anti Cash trapping cleat that simply fits either side of the shutter and prevents the trapper being fitted.

- Fits in seconds
- No tools required
- Optional screw on system
- Looks like part of the ATM
- Uses VHB double sided tape to bond to cash shutter bezel

NCR PID: TBC



Area where trapper is fitted



Cash slot with cleats fitted

Trapping Device



Scuff marks showing where device was fitted



Recovered device



Anti Cash-Trapping cleats