

DIGITAL KITCHEN SCALE


ONE
HOME COLLECTION



OPKS008 Instruction Manual


*Thank you for your choosing the electronic kitchen scale of our company. For proper use of this product and ensuring its accuracy and service life, please read this manual carefully before using it.

Features & Operations



1. Put the tray on the platform of the scale
2. Power on by ON/OFF
3. Wait until all information being displayed (as shown in the picture)

Unit Conversion



Press UNIT to change the weighing modes before or during weighing if this product has the metric system(kg,g) or the Imperial Standard (lb,oz)
Note: units are determined under the request of the dealer or market.

Thermometer


1. The temperature of laboratory will be shown on the upper right corner of the display
2. Temperature range: 0-40 °C
3. Temperature division: 0.5 °C

Tare

More items can be weighed without removing the former weighed ones from the tray. (The weight will be displayed after the first item being placed on the tray. Press Z/T to reset, then weigh the second item. Follow this step to continue.)


Condition 1: Reset

When the total weight of the items on the tray $\leq 10\%$ of the capacity, everytime press Z/T, the display will show "—" or "Og", "—" stands for the process of reset and stabilization. The reset function take effect if the display shows "Og" and "ZERO" on the lower-left corner after stabilization. The capacity wouldn't be affected during this time.




Condition 2: Tare

When the total weight of the items on the tray $\geq 10\%$ of the capacity Everytime press Z/T, the display will show "—" or "Og", "—" stands for the process of reset and stabilization. The Tare function resets and the display shows "Og" and "ZERO" on the upper-left corner after stabilization. Current capacity-maximum capacity-total weight of the items on the tray



Countdown Timer




1. When setting time, please confirm each digit by T-SET before you set the next digit, press T-SET to countdown after finishing setting or clear the previous time during countdown.
2. Timer stops when any key being pressed.
3. After countdown finishes, bell rings. The timer will stop while the product will power off automatically after 60 seconds without any operation.
4. The longest Countdown time: 99 minutes and 59 seconds.

Automatic Power-Saving



Product will power off automatically in 2 minutes without any operation or weighing change


Power Off Manually



To extend battery life, please turn off the battery after use.

NOTE: Batteries are not included.

Warning Messages



Warning reminder

1. If **Lo** displays, meaning low battery, please change your battery.
2. If **Err** displays, meaning overload, please take away the weighing item lest the scale should be damaged. (the maximum capacity will be indicated on the product)

Warning:

1. When battery is low, **Lo** will be shown, please replace batteries.
2. When overload, **Err** will be shown, please remove load on platform to avoid damage to scale. Max capacity is marked on the scale body.

LCD



Cleaning and maintenance

1. Please use wet cloth to clean the product, do not put the product in the water, or chemical, corrosive detergent
2. The plastic parts of the scale should be clean right after contact with oil, spicy material, vinegar or other stimulants (avoid contact with citrus juice).
3. Place the scale on a hard horizontal surface before use.
4. Avoid knocking , hitting or dropping the product
5. Handle this precision instrument with care.
6. Keep the product in a cool dry place.
7. Please check if the battery is in and full when the product couldn't power on.
8. The product is only for household, not for commercial use.