

### 24VDC Supply Voltage to PD6830

- + 24VDC to P+ terminal
- 24VDC to COM terminal
- Jumper from COM to S- terminal
- Chassis Ground to Enclosure Mounted Green Bolt

### Output Type 'C' Sensor to PD6830

- Red Wire (+) to P+ terminal in addition to +24VDC Supply
- Black Wire (-) to S- terminal
- White Wire (Signal) to S+ terminal
- Green wire to Earth ground




Figure 1. Connector Board

Figure 2. Sensor and Cable Assembly

