## **ASSEMBLY INSTRUCTIONS**

NOTE: DON'T TIGHTEN BOLTS UNTIL ALL PARTS ARE CONNECTED. 2 PEOPLE ARE REQUIRED WHEN ASSEMBLING

PART NO	PART IMAGE	QTY	PART NO	PART IMAGE QT	1		2
A1		1	Р	M6*15MM 12	2	-A1 Β1	
A2		1	Q	Ø M6*35MM 6		B1 ( )	
B1		1	R	м6*50мм 5		P*6	C1 C2
B2		1	Т	1		B2	
C1		1	U	2 1		R*3 0 0 0*3	Q*4 R*2
C2		1	3			(4)	V*6 5
D		1				P*4	
D1		1		C1 D	DI		
Е		1		C2		D1 E	
N	00	3					
0	Ø м6	5		Q*2		P*2	

## **ASSEMBLY INSTRUCTIONS**

NOTE:DON'T TIGHTEN BOLTS UNTIL ALL PARTS ARE CONNECTED. 2 PEOPLE ARE REQUIRED WHEN ASSEMBLING

PAR1 NO	PART IMAGE	QTY	1 2
F		2	
G		2	F F F
Н		2	
ı		2	G F,J,F
J		4	H F,J,F G,J,G H,J,H
Р	м6∗15мм	4	I,J,I /
Q	M6*35MM	8	3 4 5
S	<b>®</b>	4	Y*2
W	• •	2	Y*6 00,0
X		1	H,J N*2
Υ	<i>О</i> м6	8	Q*6

## **ASSEMBLY INSTRUCTIONS**

NOTE: DON'T TIGHTEN BOLTS UNTIL ALL PARTS ARE CONNECTED. 2 PEOPLE ARE REQUIRED WHEN ASSEMBLING

					TAILE REQUIRED WHEN AGGEWALING
PART NO	PART IMAGE	QTY		1	(2)
K		2			
L		2			Q*4-
D		1	D D1		
D1		1	D1 D	Q*2-	
М		4			M- M
0	<i>О</i> м6	4	3	4	
Q	<b>⊘</b> M6*35MM	20	R*2 - 0*2		Q*4
R	M6*50MM	4		D	
				D1	
			M-	M	