

Clear-Fusion™ V

Application Instructions

Application Instructions:

- 1 Clean and dry the surface that is to be treated – the cleaner the surface, the better the coating.
For granite, tile, porcelain, and quartz, test a small area for compatibility. If no discoloration is found, proceed to step #3.
- 2 In a well-ventilated area, apply the spray protectant and wipe Clear-Fusion™ V protective coating onto the surface with a microfiber towel using firm circular, overlapping motions, going over the entire area at least twice.
- 3 Remove any excess solution by sprinkling the surface with water and wiping it down with a clean dry cloth or paper towel until clear and sparkling.
- 4 To test the application, spray the surface, looking for uniform water beads. For areas that are not beading up uniformly, dry the entire surface and reapply Clear-Fusion™ V as needed.

Important:

If the glass to be treated is heavily stained, DFI recommends using our Restoration Powder™, along with a scrubber pad, to remove any stains and prep the surface for the Clear-Fusion™ V application.

Important:

In less-ventilated areas, apply Clear-Fusion™ V protective coating in small sections.

