

Client: INFINITY X1
File: ITM. / ART. 1600276
BLUETOOTH SPEAKER MANUAL-CC-USA-v.17

Start Date: FEB. 23, 2021 End Date: JULY 18, 2022





ALTHOUGH THIS ARTWORK HAS BEEN CHECKED FOR ACCURACY, IT IS THE RESPONSIBILITY OF THE CUSTOMER TO MAKE ALL FINAL APPROVALS. PLEASE DOUBLE-CHECK ACCURACY OF ALL TEXT, THE COLORS, ARTWORK DIMENSIONS, IMAGE AND COPY POSITIONS. ANY CHANGES MADE TO THE ART AFTER YOU APPROVE MAY RESULT IN ADDITIONAL CHARGES.

Approved by: \_\_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_\_

# **CURRENT CHECKLIST / STATUS:**

As of JULY 25 - 2022

COSTCO ENGLISH APPROVAL: YES V KELSEY PATRICK -APR.29-2021 ITM. / ART. #: YES ITM. / ART. 1600276 WARNINGS: YES V CUSTOMER SERVICE INFO: PLACED - PENDING CERTIFICATION MARKS: ADDED

MAR. 29 - ADDED MISSING GRAPHICS MAR. 31 - CHANGED DISCONNECT FUNCTION TO (CLICK TWICE) APR. 5 - Revised another image to click twice

Apr. 7 - Added new CHINA Address
-Made Robinson's changes
-Apr. 13 - Changed Japan address
APR. 29 - ENGLISH APPROVED
MAY 13 - CHANGED FL1 INFO
MAY 17 - ADDED AUSTRALIAN GUARANTEE
JULY 20 - ADDED SWEDISH ADDRESS & FREQUENCY STATEMENT

MAY 9-2022 - RUNNING CHANGE TO COSTCO ADDRESSES JULY 18- ADDED SORTING LABEL TO MANUAL - v.17 JULY 25 - UPDATED ADDRESSES (04-13-22) - V.18

AUG. 10/2021- ADDED PEAK BEAM

FL1 STANDARD NORME FL1 NORMA FL1	HIGH HAUTE ALTA	MED MOY MEDIO	LOW FAIBLE BAJA
314	700 LUMENS LÚMENES	300 LUMENS LÚMENES	100 LUMENS LÚMENES
(	2h 30min	5h	12h
	28 m	18 m	10 m
	196cd	81cd	25cd
1m		1	

1600276

Bluetooth 5.0

which it connects)

DC 5V 1A

2600 mAh

5.5 x 3.0 x 2.5 inch

5 W

≤10m (depending on operation

environment and devices to

Product Model

**Bluetooth Specifications** 

Transmission Distance

Built-in Battery

**Output Power** 

**Product Dimensions** 

USB Rechargeable Voltage

PRODUCT INFORMATION

# **BATTERY LIFE**

LIGHT ONLY 2.5 Hours 700 Lumens

**MUSIC ONLY** 12 Hours

LIGHT & MUSIC 3.5 Hours 400 Lumens

**PROBLEM** 

Unable to pair up with

other devices

The sound is rather low

or distorted

The music stops from

time to time

The Bluetooth indicator

remains off

#### FCC STATEMENT OF COMPLIANCE

WARNING: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment. This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Note: This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

SOLUTIONS

Note: (a) frequency band(s) in which the radio equipment operates: 2.4 - 2.4835 GHz.

(b) maximum radio-frequency power transmitted in the frequency band(s) in which the radio equipment operates: 4.30 dBm (E.I.R.P.).

#### **PRECAUTIONS**

- Please store and use this product at room temperature. • Do not expose this product to rain or damp
- surroundings • Prevent this product from falling as that could result in serious damage.
- Do not dismantle, repair or modify this product on your own.
- In order to avoid any risk, do not dispose this product inappropriately or expose it to fire as there is a built-in, non-replaceable lithium battery.

#### Tips

- 1. Do not turn up the volume to maximum for a long time as this could shorten the service life of this product or impair your hearing.
- 2. When encountering any fault during operation, please cut off the power supply and disconnect the USB cable to prevent further damage to the speaker or other components.
- 3. The Bluetooth transmission range or connectivity could be affected by low battery power. In that case, please recharge immediately.



**CAUTION:** Possible hazardous optical radiation emitted from this product. The luminaire should be positioned so that prolonged staring into the luminaire at a distance closer than 1.5 m / 5.1 ft is not expected.



**WARNING:** The ventilation should not be impeded by covering the ventilation openings with items such as newspapers, tablecloths and curtains. Allow at least a 10 cm gap all around the product.



**WARNING:** No naked flame sources, such as lighted candles, should be placed on the speaker.



**WARNING:** This appliance is intended for domestic household use only and should not be used for any other purpose or in any other application, such as for non-domestic use or in a commercial environment.



Importado por: tadora Primex S.A. de C.V. Blvd. Magnocentro No. 4
San Fernando La Herradura
Huixquilucan, Estado de México RFC: IPR-930907-S70 (55)-5246-5500

www.costco.com.mx

Costco Online UK Ltd Hartspring Lane Watford, Herts WD25 8JS 01923 213113

Costco Wholesale Iceland ehf. Kauptún 3-7, 210 Gardabaer www.costco.is

Costco Wholesale Japan Ltd. 2 Kakuchi, 2 Gaiku, Kaneda-Nishi 361 Urikura, Kisarazu shi Chiba, 292-0007 Japan 0570-200-800

Costco Wholesale New Zealand Limit Westgate Auckland 0814 New Zealand

\* faisant affaire au Québec sous le nom les Entrepôts Costco

415 W. Hunt Club Road

Costco Wholesale Australia Pty Ltd 17-21 Parramatta Road ´ Lidcombe NSW 2141 www.costco.com.au


Costco Wholesale Sweden AB Box 614 114 11 Stockholm

Costco Wholesale Spain S.L.U. Polígono Empresarial Los Gavilan C/ Agustín de Betancourt, 17 28906 Getafe (Madrid) España www.costco.es

> 1 avenue de Bréhat 91140 Villebon-sur-Yvette 61 80 45 01 10

Costco Wholesale Korea, Ltd. 40, Iljik-ro Gwangmyeong-si Gyeonggi-do, 14347, Korea 1899-9900

Room 1003, Block 2, 2388 Xiupu Road, Pudong New Area, Shanghai China 201315 +86-21-6257-7065



Questions, problems missing parts? Before returning to your retailer, call Customer Service:

### **CUSTOMER SERVICE**

USA: 1-866-544-4891 International: 1-760-230-5611 Hours: M-F 9AM to 5PM Pacific Time Web: www.infinityx1.com/support Email: support@infinitvx1.com

SMARTER INSIDE. BRIGHTER OUTSIDE

**Manufacturer / Fabricant / Fabricante:** 

3525 Del Mar Heights Rd, Suite 867 San Diego, CA 92130, USA


©2021 INFINITY X1 LLC\*

www.infinityx1.com








MADE IN CHINA




- 1. Check whether the speaker's effective transmission range is exceeded or there is an obstacle standing between the speaker and other Bluetooth devices.
- 1. It suggests the battery power drops quite low and retry once being recharged.
- 2. Turn it on again.







## DISCONNECT FROM PHONE BEFORE CONNECTING NEW PHONE



Speaker A or B