



**RS30 Ultra Force Feedback Racing Wheel / V3 Pro Pedals User Manual**  
**Please read all the instructions prior to use**

**Parts Included:**



**A: RS30 Steering Wheelbase**


**B: RS30 Steering Wheel**

**C: Mounting Clamps**

**D: Power Supply Cord**

**E: V3 Pedals**


## STEP 1. >>



Connect to the V3 Pro Pedals

Connect to the power supply

## STEP 2. >>



Turn counterclockwise to lock the wheel and wheelbase

## STEP 3.



Use Allen Key to lock the wheel with wheel plate/table



### RS30V3 Wheel & Pedals Calibration Steps

Step 1:

Once USB is plugged in, press the [up] + [down] + [x] button simultaneously.

Step 2:

The LED light on the wheel will start blinking and it will enter calibration mode.

Step 3:

Turn the wheel all the way to the left and right, then press the gas pedal all the way down and release, then press the brake pedal all the way down and release.

Step 4:

Press the [view] + [menu] button simultaneously to exit calibration mode  
The final step, unplug and replug the USB. The pedal should work again.  
We should have calibrated the pedal prior to sending it to you, but we will double-check on our end.

WINDOWS 11: hold view/menu for a few seconds in Windows 11 to make sure it shows up as a controller

**For more info, please visit: [gtrsimulator.com/support/](https://gtrsimulator.com/support/)**