


## MECHANICAL SKELETON 3 HANDS

### A) DISPLAY



### B) WINDING THE MAINSPRING

Automatic winding watch can be hand wound by turning the crown in position 1. Wind 15-20 times and it will start to move naturally after shaking slightly.

### C) TIME SETTING

1. Pull the crown to position 2.
2. Turn the crown clockwise / anti-clockwise to set hour and minute hands.
3. Push crown back to position 1.



EARNSHAW

-1805-