


IMPORTANT
INSTRUCTIONS AND WARRANTY INFORMATION
PLEASE READ

FAILURE TO FLUSH THE POWER STEERING SYSTEM WILL VOID YOUR WARRANTY.

When flushing the system pour some of the oil from the system through a napkin or coffee filter. If metal particles are found, the pump must be replaced. Proof that this procedure was followed must be noted on the repair order for warranty to be valid. All port threads were in good condition after assembly and testing. Use proper torque specifications when tightening the power steering hose fittings. NOTE: NO warranty credit will be issued for stripped threads.

The enclosed unit can be used on vehicles with either manual or automatic transmissions. The bracket on the rack cylinder (see picture below) is required on manual transmission applications and will not interfere with installations on automatic transmission vehicles.



Due to random pinion locations on the OEM steering gears, it may be necessary to remove and re-center the steering wheel after installing the gear.