

# REGAL<sup>®</sup> SILVER SHINE ALUMINIUM

A protective and decorative economical aluminum coating for application on interior and exterior surfaces. It has good light reflection properties including mild heat resistance. Suitable for surfaces like storage tanks, refineries, bridge fences, light poles, and industrial and moderate marine service.

**PACK SIZE:** 0.25, 0.91, 3.64L

**COLOR RANGE:** Silver

**COMPOSITION (NOMINAL):**

Pigment: Leafing aluminum paste

Binder: Modified Alkyd Resin

Solvent: White Spirit

**DRYING TIME:**

Depends on temperature humidity, air movements, and film thickness

Touch Dry: 2-4 Hours

Recoat: 6-8 Hours

**THEORETICAL COVERAGE:**

A guide to the theoretical coverage which can be achieved under normal conditions is 13-14m<sup>2</sup>/liter/coat.

**FLASH POINT** 34°C

**APPLICATION:** Spray

**THINNING:** Conventional spray 20-25 %

**CLEANING UP:**

Clean all equipment with White Spirit /super petrol immediately after use.

**SURFACE PREPARATION:**

Scuff the surface with the sand paper. Remove all dirt, grease by air blow and wipe with rag soaked in white spirit. Apply one coat of Primax Synthetic Undercoat, scuff and clear and then apply Primax silver shine aluminum Paint in two coats with suitable interval.

**SAFETY, HEALTH AND ENVIRONMENTAL INFORMATION**

Keep container tightly closed and upright to prevent leakage when not in use. Don't breathe in vapors and sanding dust.



**PRIMAX**<sup>TM</sup>  
**PAINTS**

Cartridge mask should be worn when rubbing down. Provide adequate ventilation during application and drying. If you experience difficulty in breathing, move to fresh air. Don't permit smoking in the vicinity. Avoid contact with eyes and skin. Wear gloves and goggles during application or sanding. In case of contact with eyes, flush with plenty of water and seek medical advice. To remove splashes from the skin, use soap and water or a recognized skin cleaner. Protect from extremes of temperatures. Store in a cool dry place but also protect from freezing. In case of fire, use foam, dry powder, CO2 fire extinguisher. Keep away from the source of ignition. Close the container tightly after each use. Keep out of reach of children. In case of an accident, collect spillage using sand or clay and dispose of paint waste in accordance with appropriate environmental quality requirements.

Any advice recommendations, information, assistance or service provided by Progressive Paint Industries in relation to goods manufactured or marketed by it or their use or any applications is given in good faith without expressed or implied warranties.

**NOTE:**

Color and high sparkle metallic finish depends very much on the right pressure, the distance between the spray gun and the surface, the viscosity of the paint, and the method of the application of the painter.

