GIMBEL AUTOMATION

Automatic Conveyor Loading System for Five-Axis CNC Mills



Benefits of Conveyor Loading System (CLS)

- Sets up Automated Tending in Minutes
- Your **Machine Loads itself** using Spindle Grippers
- **Easily Swaps** Between Different Setups & Stock
- Parts Unload onto Return Tray Automatically

Optional Accessories

- Safety Light Curtains
- Optional Complete PLC Integration w/ Touch Screen
- Optional Part Flipper for Finished One-Op Parts
- Optional Air Knife
- Integrated Auto-Door



(CZ)

747-257-9465 () GimbelAutomation.com

The **Automatic Conveyor Loading System (CLS)** for Five-Axis CNC Mills enables continuous part loading and unloading, with setups and stock swaps taking only minutes. Part stock sits on a self-advancing conveyor, which is advanced into the machine head's travels, allowing the CNC machine to load and unload its parts using Gimbel Automation Spindle Grippers.



Automatic Conveyor Loading Sytem Kit Includes:

- CLS Unit
- Adjustable Fences and Return Table for Finished Parts
- M-Code Machine Control Integration
- (Full PLC w/ Safety Interlocks Available)

Technical Specs	
Conveyor Length	48"
System Dimensions	49" W x 24" D x 40" H
System Weight	205 lbs
Max Total Part Weight	150 lbs

Advance through the mill's side door, allowing for **seamless integration** with your existing setup. <u>Makes automated</u> <u>sequential production as simple as</u> <u>running one part.</u>

Accessories for Automatic Conveyor Loading System



Order Online Today!

747-257-9465 () GimbelAutomation.com