# **GIMBEL** AUTOMATION

## **CNC VACUUM PART GRABBER**



## Why CNC Vacuum Part Grabber?

- **Excellent** for very tiny or very large parts
- A large suction cup can load and unload very heavy or cumbersome components automatically
- Reduce setup operation
- Increase Automation
  Productivity

## Vacuum Part Grabber Features

- Aids loading & unloading parts
- Creates up to 12 PSI of vacuum
- **Complete Kit** comes with 4x sizes of suction cups



(CD)


**Order Online Today!** 

747-257-9465 () GimbelAutomation.com

# **GIMBEL** AUTOMATION

#### **CNC VACUUM PART GRABBER**

Our Patent-Pending **Vacuum Part Grabber** is the only solution on the market that turns your CNC Machine into an automated loading cell with little to no adjustment. The proprietary Venturi Generator creates up to 12 PSI of vacuum, and is turned on by simply turning on your machine's Through Spindle Air Blast.



#### **Complete Kit Includes:**

- 1x CNC Vacuum Part Grabber
- 4x Sizes of Suction Cups
- 1x Hard Pelican Case
- 1x 3/4" MariTool Holder (OPTIONAL)

Technical Specs	
Max Vacuum Achievable	12 PSI
Vacuum Port Size	1/8" NPT
Shank Diameter	3/4"
Air Pressure Required	75 - 140 PSI

## AUTOMATION. MADE EASY.

### **Accessories for CNC Vacuum Part Grabber**

