



BMW / Toyota B58 Camshaft Picker

BMW has released these engines in several revisions. To simplify things, the Kelford team named these revisions Gen 1, Gen 1.5 & Gen 2. Please see the table below for help selecting the correct cams for your model. For any additional help please contact your 5150 sales team, Sales@5150AutoSport.com.

Model	Years	Gen 1 (July 2017 & Earlier)	Gen 1.5 (August 2017 & Later)	Gen 2	Key Gen 1
F20 M140i	2016 - 2019				Gen 1.5
F22 M240i	2017 - 2021				
G42 M240i	2022 -				Gen 2
F30 340i	2016 - 2018				
G2O M340i	2019 -				Cam Bolts & Timing Chain
F32 440i	2016 - 2020				Gen 1 Cam Bolts
G22 M440i	2021 -				have M22 thread & single piece Timing Chain
G30 540i	2017 - 2019				
G30 LCI 540i	2020 -				Gen 1.5 Cam Bolts have M21 thread & 2-Piece timing chain, but are otherwise
G30 540i 48V	2021 -				
740i	2017 - 2019				
740i	2020 -				Gen 1
740i 48V	2021 -				Gen 2 Cam Bolts and Timing Chain are the same as 1.5, but with revised Cam Trigger and Fuel Pump Lobe
840i	2018 -				
840i 48V	2021 -				
X3 M40i	2018 - 2019				
X3 M4Oi	2020 -				
X4 M40i	2019				
X4 M40i	2020 -				
X5 40i	2019 -				
X6 40i	2019 -				
X7 40i	2019 -				
Z4 M4Oi	2019 -				
A90 / Mark 5 Supra	ALL				