



SERVICE BULLETIN

SP2017-005
Revision 1
November 7, 2018

Before performing any service always follow applicable safety precautions.

Models No Longer Supported

Affected Products:	BBR-79	All serial numbers.	Effective 10/01/2017
	BMJ-6E	All serial numbers.	Effective 10/01/2017
	BMJ-15E	All serial numbers.	Effective 10/01/2017
	BMJ-200E	All serial numbers.	Effective 10/01/2017
	BMJ-200I	All serial numbers.	Effective 10/01/2017
	BMJ-350I	All serial numbers.	Effective 10/01/2017
	BMJ-1000	All serial numbers.	Effective 10/01/2017
	OT-300	All serial numbers.	Effective 10/01/2017
	SC-600	All serial numbers.	Effective 01/01/2019
	SPX-500	All serial numbers.	Effective 01/01/2019
	UXR-100	All serial numbers.	Effective 10/01/2017
	XLR-350	All serial numbers.	Effective 10/01/2017

Affected Serial Range: See above.

Related Issue #: N/A

Revision 1: SC-600 and SPX-500 added

Issue Description:

On the indicated dates, the above smokers will no longer be supported by Southern Pride. This includes availability of replacement parts and technical support. Remaining quantities of replacement parts will be sold until the effective date, or until the current inventory is depleted. The sole exception is 10" x 34" chrome product racks (part 970005). This part will continue to be available past the effective date.

Actions Required:

Order any desired replacement parts for the above smokers by the effective date.

Additional Comments:

Replacement parts that are common with other models would still be available for the above smokers.

Secondary Distribution:

Service technicians within the Distributor's organization.

Service companies.

For Additional Information:

Southern Pride Technical Support: (800) 437-2679