

Keep your workers safe and protect your equipment with InoRAC2, Universal Racking Device. Avoiding worker Arc Flash Hazards is important and necessary.

InoRAC2 helps by creating a **Substitution** of the Arc Flash Hazard. In essence you replace the worker with a machine in front of the breaker cell. The InoRAC2 allows the worker to rack the breaker from up to 75 Ft away using the remote control interface.

See the Hierarchy of Controls below. Reference <http://www.cdc.gov/niosh/topics/hierarchy/>



Contact us for more information and to book an on-site demonstration of the InoRAC2

Web: www.LeadingEdgeSales.ca and

http://www.inolect.com/Remote_Racking.html

Toll Free: 1-866-313-9004

E-Mail: info@leadingedgesales.ca