

Notes About the Assembly

The P#'s refer to plate numbers in the STL files.

Everything is meant to press-fit, so don't be afraid to push hard.

If any of the parts are too tight or loose, simply size them down or up by 0.5-1% and try again. Matte filament works the best.

If you're using a printer that can cancel failed objects, you may want to split the plates into objects to take advantage of that, just in case.





