



Comfort Flow™ & Comfort Scrape™

Washing Instructions

Comfort Flow and Comfort Scrape mats are fully launderable mats that perform great as anti-fatigue and flow-through mats in both wet and dry environments.

- These mats can be washed periodically to remove oil, grease and soil.
- The formula shown below does not require extensive mechanical action or drying.

Process	Comments	Time	Water Level	Temperature
Flush		2-3 Min.	High	120° F (49°C)
Break		5-10 Min.	High	140° F (60°C)
Rinse		2 Min.	High	120° F (49°C)
Rinse		2 Min.	High	Cold

- The main purpose of this formula is to dissolve grease residue by using hot water to emulsify oils and grease.
- Lay mats flat following removal from washer. Allow to cool before rolling.