

BLACKMAN CRUZ


WORKSHOP *LOS ANGELES*

CARE INSTRUCTIONS

THANK YOU FOR YOUR RECENT PURCHASE FROM OUR BC WORKSHOP COLLECTION. THE ENTIRE BC WORKSHOP SERIES IS DESIGNED AND MANUFACTURED IN LIMITED QUANTITIES IN LOS ANGELES BY LOCAL ARTISANS. EACH PIECE IN OUR COLLECTION IS INDIVIDUALLY CRAFTED. AS A RESULT, SLIGHT VARIATIONS IN PATINA, FINISH AND GRAIN MAY OCCUR.

COMPASS MIRROR

BRASS FRAME WITH
BRONZE COMPASS FINIALS AND MIRROR
48"H X 37"W X 3"D



CLEANING INSTRUCTIONS FOR HAND-PATINATED BRONZE

PATINATED BRONZE PRODUCTS ARE SENSITIVE TO MOISTURE AND DIRECT HEAT. AVOID PLACING PRODUCT IN DIRECT CONTACT WITH HEATING VENTS, INTENSE DIRECT SUNLIGHT OR AREAS EXPOSED TO MOISTURE OR DENSE HUMIDITY. PATINATED BRONZE CAN BE CLEANED WITH A MICROFIBER CLOTH. USE PLEDGE OR HOT SOAPY WATER TO DAMPEN A CLEAN RAG TO CLEAN. AVOID USING HIGHLY ABRASIVE SCRUBBING MATERIALS, METAL BRISTLED BRUSHES, STEEL WOOL OR BLEACH-BASED CLEANERS. MATERIALS SUCH AS THESE WILL SCRATCH THE SURFACE OF THE BRONZE.

CLEANING INSTRUCTIONS FOR BRASS FRAME

PATINATED BRONZE PRODUCTS ARE SENSITIVE TO MOISTURE AND DIRECT HEAT. AVOID PLACING PRODUCT IN DIRECT CONTACT WITH HEATING VENTS, INTENSE DIRECT SUNLIGHT OR AREAS EXPOSED TO MOISTURE OR DENSE HUMIDITY. PATINATED BRONZE CAN BE CLEANED WITH A MICROFIBER CLOTH. USE PLEDGE OR HOT SOAPY WATER TO DAMPEN A CLEAN RAG TO CLEAN. AVOID USING HIGHLY ABRASIVE SCRUBBING MATERIALS, METAL BRISTLED BRUSHES, STEEL WOOL OR BLEACH-BASED CLEANERS. MATERIALS SUCH AS THESE WILL SCRATCH THE SURFACE OF THE BRONZE.

ALL PRODUCTS ARE CONSIDERED TO BE IN GOOD CONDITION AND ERROR-FREE WHEN DELIVERED. CLIENT SHOULD INSPECT ALL DELIVERIES IMMEDIATELY UPON ARRIVAL, AND SHOULD MAKE NOTE OF ANY DAMAGE WHEN SIGNING FOR THE PRODUCT DELIVERY.

ALL BC WORKSHOP PRODUCTS CARRY A ONE-YEAR WARRANTY. IF CLIENT FINDS A MATERIAL DEFECT IN ANY PRODUCT, PART OR COMPONENT WITHIN ONE (1) YEAR OF PURCHASE, PLEASE CONTACT BLACKMAN CRUZ. BLACKMAN CRUZ WILL NEED TO DETERMINE IF CARE, MAINTENANCE, INSTALLATION AND OTHER FACTORS CONTRIBUTED TO PRODUCT DEFECT.