

# Resins Plus ™ Resins Plus RS2750 Polyurea Basecoat

### PRODUCT DESCRIPTION

Polyurea Basecoat is a two components Polyurea coating designed to maintain the integrity of concrete surfaces. It exhibits very good mechanical properties. Available Colors: Tan & Grey. Clear and others colors available by request.

APPLICATIONS Polyurea Basecoat is formulated as a high solids system for industrial floor shops, car washes, mechanical rooms, areas of light manufacturing, or where concrete repair is needed.	ADVANTAGES  • Very good adhesion with various substrates  • Cure at low and high temperature  • Good chemical resistance  • Zero VOC		
PACKAGING	STORAGE		
Polyurea Basecoat is packaged in factory proportioned packaging for easy handling and	All components should be stored in dry, temperature controlled areas between 12-28°C. Do not expose to		
mixing.	freezing or excessive high heat		
3 gallon kit and 15 gallon kit	noozing or oxioosino mgn nodi		
J Squilott kii dild 13 gallott kii			

TECHNICAL DATA @ 75°F				
% SOLIDS BY WEIGHT	100%	VOC CONTENT	41.77 g/liter	
GEL TIME 100G	30-60 Minutes	MIXING RATIO BY VOLUME	2:1	
SUGGESTED # OF COATS	2-3	RECOAT TIME (MIN/MAX)	90-120 Minutes / 24 Hours	
FOOT TRAFFIC	24 Hours	LIGHT TRAFFIC	3 Days	
FULL CURE	7 Days	SHELF LIFE	12 Months unopened	
COMPRESSIVE STRENGTH	6800 psi	BOND RESISTANCE	268 psi	
ASTM D695		ASTM D4541		
TENSILE STRENGTH	5500 psi	HARDNESS (SHORE D)	85-90	
ASTM D638		ASTM D2240		
PERMEABILITY	0.3%	ELONGATION	6.7%	
ASTM D570		D638		
ABRASION RESISTANCE	0.10 g	MIXED VISCOSITY	1000-1200 cps	
ASTM D4060				

PRIOR TO USE APPLICATOR MUST ALWAYS READ AND FOLLOW WARNINGS AND INSTRUCTIONS. MOST UP TO DATE PRODUCT TECHNICAL DATA SHEETS, PRODUCT LABELS AND MATERIAL SAFETY DATA SHEETS WHICH ARE AVAILABLE UPON REQUEST BY CALLING TECHNICAL SUPPORT DEPARTMENT.

## **SURFACE PREPARATION**

Surface must be clean, sound and dry. Prior to coating a floor all trowel marks and surface imperfections must be removed to produce a smooth & uniform surface. Proper surface preparation is critical to ensure an adequate chemical bond to substrate. Substrate must be dry and free of all wax, grease, oils, fats, soil, contaminants, loose or foreign matter and laitance. Concrete should be cleaned and prepared using a shot blast machine or adequate grinding equipment to achieve a CSP-3 to CSP-4 profile as per ICRI guidelines. Compressive strength of concrete should be at least 3,500 psi (24 Mpa) @ 28 days and at least 215 psi (1.5 Mpa) in tension at time of product application.

**Polyurea Basecoat** is supplied in factory proportioned quantities, greatly reducing the risk of applicator error during mixing.

- Step 1 Mechanically premix PART A (resin) with an appropriate slow speed drill equipped with a Jiffy Mixer, for 1 minute.
- Step 2 Slowly empty entire content of PART B into container holding PART A and continue to mix for minimum 3 minutes

#### DO NOT MIX MORE MATERIAL THAN CAN BE APPLIED WITHIN WORKING TIME LIMITS.

#### **POTLIFE**

After mixing, Polyurea Basecoat has a pot life of approximately 40 minutes at 75°F. It is important to use it once mixed. Pot life depends on ambient and surface conditions.

#### **APPLICATION**

Pour the Polyurea Basecoat on the floors and spread the material with a squeegee, then roll back.

## **CURING**

In broadcast system, Polyurea Basecoat sets in approximately 90-120 minutes at ambient temperature.

#### PRECAUTIONS & LIMITATIONS

Prior to application, measure and confirm Substrate Moisture Content, Ambient and Surface temperatures and Dew Point.

**Substrate Moisture:** Moisture within substrate must be  $\leq 4\%$  by mass as measured by Tramex® type concrete moisture meter on mechanically prepared surface.

**Dew Point:** AVOID CONDENSATION. The substrate must be at least 5°F above Dew Point to reduce risk of condensation. Condensation may lead to failure in adhesion. Avoid situations where substrate temperature is considerably lower than ambient temperature.

Do not add thinners or solvents to mix. Do not add water. Dispose of waste materials in accordance with government regulations. The use of safety glasses and protective gloves is required. In case of contact, flush areas with abundance of water for 20 minutes and seek medical assistance. Wash skin with soap and water. Use only in well ventilated areas.