T15 W/Lines

TOYOTA GENUINE

PARTS, SERVICE & ACCESSORIES

HILUX DOUBLE CAB UTILITY WITH SPORTS BAR

February 2005 production onwards

Installation Instructions for Hard Tonneau Cover USE IF UTE HAS A UTELINER



Accessory Part No. PZQ70 89315


Installation Time: Approx. 70 mins

Place these instructions in vehicle's glove box after installation is complete.

Parts List | Important : Check contents of kit before commencing fitment and report any discrepancies

Item	Component Name	Part No.	Qty	Pre- fitted
1	Hard Tonneau Cover	PZQ70 89315HT	1	×
2	Front Hinge	PZQ70 89010FH	2	1
3	Lock Kit	PZQ70 89010LK	2	1
4	Lock Bracket	PZQ70 89010LB	2	×
	-Self Drilling Screw		4	×
5	250N Gas Struts	PZQ70 89010GS	2	×
6	Lid Strut Bracket	PZQ70 89010LS	2	×
	- M6 Bolt		6	1
7	Body Attach Bracket	PZQ70 89010BB	2	×
	- Self Drilling Screw		4	×
8	Front Bar Assembly Set	PZQ70 89015FB14	1	×
	-Self Drilling Screw		9	×
9	Toyota Badge	PZQ70 89010TB	1	1
10	LHS Moulded Insert	PZQ70 89015ML	1	×
11	RHS Moulded Insert	PZQ7089015MR	1	×
12	Moulded feet cups	PZQ70 89010FC	4	×
13	LHS Infill Support Bracket	PZQ70 89010SL	1	×
	- 45 mm M8 Bolt and M8 washer		2	×
	-25 mm M6 Bolt and Nut		3	×
14	RHS Infill Support Bracket	PZQ70 89010SR	1	×
	- 45 mm M8 Bolt and M8 washer		2	x
	-25 mm M6 Bolt and Nut		3	×









Tools Required:

- Masking Tape and Marking Pen
 - Tape Measure
 - Cordless Drill
- 2 mm Drill Bit (with 5 mm stop)
- #2 Philips Screwdriver
- 5 mm Allen Key
 - 10 mm open end spanner
- Torque wrench
- Centre Punch
- Jig Saw
- Clear or black silicone

Care Instructions:

- Read Instructions Fully before commencing installation.
- Refer to manufactures instructions applicable to power drill
 - Wear appropriate safety goggles when drilling
- Protect Tub floor against scratches during installation process.

ISSUE 3: 26 OCT 2006


Part No: PZQ70 89315-with Sports Bar with Ute Liner



TOYOTA HILUX DOUBLECAB UTILITY WITH SPORTS BAR

PARTS. SERVICE & ACCESSORIES

Accessory Part No. - PZQ70 89315



Important:




Use these instructions, if Ute has a Uteliner.

Never fit Front Bar Assembly of tonneau over a Uteliner

CAUTION:

Over tightening fasteners attached to the hard tonneau cover may damage the threaded inserts. Please use recommended tightening torques where specified.



Important:




Remove sportsbar from vehicle

Recommended:

You should leave the protective plastic film on the lid, peel back the protective plastic film 100 mm from around all edges.

Remove the remaining protective plastic film only at completion of installation (see step 15).

With Ute liner removed, fit Front Bar Assembly (FBA) first. Align bar along front of tray, ensuring ends of bar are flush with sides of tray. Remove white paper tape from rubber seal and attach the FBA using nine self-drilling screws (supplied) through holes pre-drilled in bar. Apply clear or black silicone to any gaps between the FBA and the



vehicle to prevent water entry.

Refer to Fig. 1 and Fig 1A

Important:



For all ute liner cutouts, mark a line with white or yellow marker on liner.




Fig. 2A: Initial cut of ute liner front section (RHS shown)




Fig. 2B: Initial cut of ute liner front sec-tion (LHS shown)

2A. Measuring from front edge of ute liner rail lip, mark a line 100 mm back and 40 mm down the inside face of the liner (see Fig. 2A).

Repeat this for LHS (see Fig. 2B)

Keeping the same depth of 40 mm, continue the line as shown along the inside of the front face of the liner from the RHS front corner to the LHS front corner.

Using a jig saw, cut the liner along the marked line and remove blackened section as shown.




TOYOTA GENUINE

HILUX DOUBLECAB UTILITY WITH SPORTS BAR

Accessory Part No. - PZQ70 89315


PARTS, SERVICE & ACCESSORIES



2B. Measuring from the edge of the first cut, mark a line 115mm backwards from cut edge and 50mm down the inside face of the liner (see Fig. 2C). Cut along line as marked.


50mm

Fig. 2C: Secondary cut (RHS shown)



2C. Fig. 2D shows the shape of the correctly cut ute liner.

Repeat this step for LHS.






Fig. 2E: Final cut of ute liner (RHS shown)

2D. Measured from the edge of the secondary cut, mark a line 365mm backwards from the cut edge (see Fig.

Mark a line as per Fig. 2F.

Using a jig saw, cut the liner along the marked line and remove "T" section as shown.

Repeat this step for LHS





Fig.2F:Measurement for cutting "T" Section



Reinstall ute liner to vehicle.

ISSUE 3: 26 OCT 2006

Part No: PZQ70 89315-with Sports Bar with Ute Liner

liner.


Page 3 of 9



TOYOTA GENUINE HILUX DOUBLECAB UTILITY WITH SPORTS BAR

PARTS, SERVICE & ACCESSORIES


Accessory Part No. - PZQ70 89315



3. Re-install trimmed Uteliner so it fits under the Front Bar Assembly (FBA) of the Tonneau.


Never fit FBA over Uteliner

The gas strut bracket are fitted through the Uteliner



3A. Hook tape measure over front edge of tub, measure along top edge of tray 1040mm then down 30 mm and mark the ball position for the gas strut bracket. Position the gas strut bracket accordingly, mark both mounting holes and centre punch


Refer to Fig. 3A and Fig. 3B



3B. Using a 2 mm diameter drill bit set to 5 mm drill stop. Drill two pilot holes. Attach small gas strut bracket using self drilling screws provided.

Repeat process on other side of tray.

Refer to Fig. 3B and Fig.3C




Attach small shaft end of gas strut onto gas strut brackets, by clicking them in place. Refer to Fig. 4 with regard to strut orientation.



HILUX DOUBLECAB UTILITY WITH SPORTS BAR

Accessory Part No. - PZQ70 89315




5. Turn the sportsbar upside down.

Remove all the moulded feet cups from the sportsbar.

Refer to Fig. 5





For front legs of the sport bar, remove inside bolt and loosen outside bolt.

Refer to Fig. 5A

Fig.5A




Fig.5B

5B. For rear legs of sport bar, remove inside bolt.

Refer to Fig. 5B

Important:



Step 5C must be followed to ensure a water tight seal between the moulded feet cups and the moulded inserts.

5C. Apply a small bead of silicone on inside of the moulded

On underside of the moulded feet cups, apply a small

feet cups around internal corner.

bead of silicone around slot and holes .

Inside of moulded feet cup




Underside moulded feet cup



Refer to Fig. 5C

Fig.5C



Fit the moulded feet cups supplied with the fitting Kit. For the front legs, turn the feet to outside direction.

Refer to Fig. 5D

Loosen eight bolts of the black sportsbar channel.



TOYOTA GENUINE HILUX DOUBLECAB UTILITY WITH SPORTS BAR

PARTS. SERVICE & ACCESSORIES

Accessory Part No. - PZQ70 89315

Fla.5E





The painted moulded inserts have been covered with a blue tape to protect the paint from damage during fitment. Please remove the protective tape after fitment (refer to step 14).

Install the moulded insert by placing it at the front feet first. Refer to Fig. 5E

Refer to Fig.5D for correct orientation of moulded insert.




Fig.5F

Lift up the moulded insert and place it onto the rear foot. Straighten front mounting brackets of sportsbar.

Refer to Fig. 5F







Be careful not to scratch the painted moulded insert on the sportsbar

Tighten sportsbar mounting out side bolts to 18 Nm. Repeat process on other side of Sports Bar.

Refer to Fig. 5G





Refer to Fig.5H and Fig.5J for correct orientation for this bracket.





Fig.5H

5J. For installation of support bracket on moulded insert, place steel support bracket on the underside of moulded insert. Install by using two 45 mm M8 bolts and M8 washers supplied with fitting kit, fastening one at the front and one at the rear foot. Do not fully tighten.

Repeat process on other side of Sports Bar

Refer to Fig. 5H



5K. To install the adjustment bolts on the infill support brackets (6 x 25 mm M6 Bolts with nuts supplied in fitting kit). Fasten nuts on bolts and screw the bolts into the threaded holes of the infill support bracket until the bolts touch the metal plates fixed to the underside of the moulded insert

Repeat process on other side of Sports Bar

Refer to Fig. 5J




TOYOTA GENUINE


HILUX DOUBLECAB UTILITY WITH SPORTS BAR

PARTS, SERVICE & ACCESSORIES

Accessory Part No. - PZQ70 89315




Using two people, position sportsbar assembly as shown in Fig.5K.



5M. Install the sportsbar by using bolts supplied with the sports bar. Do not fully tighten.

Refer to Fig. 5L






Remove the hinge tongues from the lid (four Allen key bolts on each side). Place hinges tongues into hinge slot already fitted to the vehicle

Refer to Fig. 6





Refer to Fig. 7




Fig.7

Important:



DO NOT over tighten screws. Recommended tightening torque is 1 to 3 Nm




Fig.8

8. Place hard Tonneau cover into position, ensuring uniform gap conditions between cover and infill panels, as well as between cover and vehicle body.

Refer to Fig. 8



TOYOTA GENERAL HILLUX DOUBLECAB UTILITY WITH SPORTS BAR

Accessory Part No. - PZQ70 89315

PARTS. SERVICE & ACCESSORIES




Fig.8A

8A. Reinstall hinges and washer plates to the lid from the inside of the tub.

Refer to Fig. 8A

Important:



DO NOT over tighten bolts. Recommended tightening torque is 6Nm



Inside tighten to 10 Nm

Fig.9



While remaining inside of the tub, tighten sportsbar mounting bolts. Inside 45 mm M8 bolts tighten to 10Nm.

Refer to Fig. 9

While remaining inside of the tub, tighten bolts to 18 Nm

Refer to Fig. 9A

Refer to Fig. 10





Fig.9A



Re-tighten 8 channel bolts at the top of the sportsbar to 10Nm.

10. With the lid opened, attach the cylinder end of each gas strut onto the mounting brackets attached to the lid by clicking into



Important:

Important:

place

To remove the lid from the vehicle, detach the gas struts from the lid. This is done by inserting a small screwdriver under the metal spring clip on the strut and easing it out sufficiently to allow the strut to be popped off the ball (Refer to Fig 10 A). From inside of tub, remove 4 bolts from each hinge bracket.

Ensure someone is supporting the lid when detaching.

Never completely remove the metal spring clip from the gas strut end, and never force the strut off the ball.





Fig.10A




TOYOTA GENERAL HILLUX DOUBLECAB UTILITY WITH SPORTS BAR

PARTS, SERVICE & ACCESSORIES

Accessory Part No. - PZQ70 89315





- 10A. With the lid closed, adjust six adjustment bolts (25 mm M6 three on each side) from inside the tub until no light can be seen through the join (as indicated by arrows) between lid and inserts. Using M6 nuts, lock bolts into place. Refer to Fig. 10B
- 11. Close lid and check it fits snugly and evenly around all sides. Make sure it also fits down snugly over the tailgate. If it does not, then adjust as follows:
- Open lid, disconnect struts from lid. a.
- Loosen four Allen key bolts on each side of the two hingel b. tongues on the lid.
- Adjust closed lid. From inside the tub, re-tighten the Allen head
- Open lid and reattach gas struts.
- Using a clean rag wipe off any excess silicone around the e. moulded feet cups being careful not to scratch paint on the moulded insert.





DO NOT over tighten the Allen head bolts. Recommended tightening torque is 1to 3 Nm







Flg.12

13. Close the lid and try the locks. You may need to adjust the lock brackets on the Ute tub up or down. When correctly adjusted, you should need to apply slight pressure to the lid in order to operate the locks. Refer to Fig. 12 and 12A





Excess tension could damage the lock





Your Ute should now look fantastic with its new IId fitted. Remember, when removing and re-fitting your lid ensure that the hinges are fully engaged to avoid damaging or bending them and follow "Important!" instructions on page 8.





Flg.12A

Important:

NEVER DRIVE WITH LID OPENED OR IN AN UNLOCKED POSITION

PAINT CARE INSTRUCTIONS:

YOUR NEW PAINTED HARD TONNEAU COVER HAS BEEN COVERED WITH A PLASTIC FILM TO PROTECT THE PAINT FROM DAMAGE. IT WILL REQUIRE CLEANING AND POSSIBLY LIGHT POLISHING AFTER THE PROTECTIVE FILM HAS BEEN RE-MOVED. USE POLISH AS PER NEW PAINT ON A NEW VEHICLE. WASH LID USING WATER AND NORMAL CARWASH DETER-GENT AND POLISH WITH AN AUTOMOTIVE POLISH.