

Whittle CNC

Big Results

Laser AddOn Assembly

KickStarter Edition

******WARNING******

Always wear the supplied safety glasses when the laser is attached, even if the machine isn't engraving.

The glasses are specific to the laser provided and not all safety glasses protect against all wavelengths of lasers.

During control board booting/restarts the laser will power on briefly. This is caused by chip pin initialization.


******WARNING******

Parts List

Laser Bag

Laser

Laser Attachment




Take the end of the Laser and Insert it into the base of the laser attachment.

Insert the longer screw and secure with the hex nut.



**Attach the Laser Board to the Laser attachment in the following configuration:
Hex Screw, Board, Spacer, Laser Attachment.**



Attach the Cable to the Control Board. Green > GND, Black > Pin12, Red > 5v

