

**Creating Performance Solutions** 

13929 East 166th Street • Cerritos, California, USA 90702-7666 • Tel (562) 926-1010 • Fax (562) 926-9486 • www.iccink.com

## **FEATURES**

#### Ready for use, High Performance plastisol formulated for Ultra High speed automatic printing.

- Very creamy and short bodied, with low tack and for ease of printing, a greatly improved shear.
- Well suited for high definition and resolution, fine detail and halftone printing.
- Faster production speeds with less pressure. Can be printed through finer mesh counts for faster production speeds with less pressure.

## 7600 LF\* COLORS

7628 S. Drake Red 7602 S. Lt. Gold 7617 Baja Black 7604 Rebel Red 7618 Island Blue 7630 Dark Grey 7606 National Red 7620 C. Orange 7646 Scarlet 7608 Bear's Navy 7622 Kelly Green 7666 Royal Blue 7610 Dark Navy 7623 Lemon Yellow 7668 Navy Blue 7612 Violet 7624 Lt. Royal 7673 Kelly Green 7614 Brock Red 7626 Bt. Orange

7616 Graphics Purple 7627 Golden Yellow
\*LF (Lead Free) Contains less than 90 ppm lead.

Application & Storage Information	
RECOMMENDED FABRICS	Light colored 100% cotton or cotton/polyester blends. Use an underbase for printing dark fabrics.
INK APPLICATION	Colors should be printed without any modifications. If thinning is required, use 1099LF LB Lo-Bleed Reducer (1% to 3% by weight).
SCREEN MESH AND EMULSION	110 to 305 t/in 43 to 120 t/cm Monofilament Any direct or indirect lacquer resistant emulsion. Use 35 to 70 micron capillary film for best results.
SQUEEGEE	60-70 Durometer: Sharp Edge 60-90-60 or 70-90-70 Triple Durometer: Sharp Edge
CURE TEMPERATURE	325° (163°C) Entire ink film. Test dryer temperatures and wash test printed product before and during a production run.
CLEAN-UP	Mineral Spirits or any environmentally friendly plastisol screen wash.
PRODUCT PACKAGING	1 Gallon, 5 Gallon, or 30 Gallon Containers.
STORAGE OF INK CONTAINERS	Recommend storage at 65°F to 90°F (18°C to 32°C). Avoid storage in direct sunlight. Keep containers well sealed.
PRODUCT MSDS	Refer to material safety data sheet MSDS8.

#### SPOT FLASHING

The 7600 inks will spot dry, with very low after flash tack, in 3 to 8 seconds depending on the spot dryer used. Too much heat / time may cause the ink to become sticky after flashing. Adjust flash unit accordingly. When spot drying, the ink should be just dry to the touch, with no lift off, but not totally fused. Totally fusing any of the flashed colors may cause inter-coat adhesion problems with the inks printed on top of the flashed ink. Final curing / fusing will occur in the dryer.

# **IMPORTANT INFORMATION**

- 1. Use an underbase print when printing 7600 inks onto dark fabrics. Use 771LF, 774LF, 7031LF or 7034LF white as an underbase ink. To achieve a softer hand and faster production speeds, print underbase ink through finer mesh counts 230 to 305 t/in or 90 to 120 t/cm.
- 2. The 7600 inks are low bleed inks, not non-bleed inks. On some types of fabric, bleeding or dye migration may occur. Always test print the fabric to be printed before beginning production. Bleeding or dye migration may not occur right away.
- 3. Excessive squeegee pressure will drive the 7600 inks through the fabric being printed. Adjust squeegee pressure, angle and off-contact to insure proper shear and lay down of printed ink. Proper settings of squeegee, flood bar and off-contact will improve performance, improve screen life and squeegee durability.
- 4. Adding too much reducer or other additives to the 7600 inks may cause curing/fusing or increased dye migration problems.
- 5. The 7600 inks are easy to print when compared to other inks and can be printed through finer mesh counts. This means less ink usage and faster production times, a real money saver. Using finer mesh counts also means a softer hand of the finished product.