


ASSEMBLY INSTRUCTION







Step2



Step3



Finished



ALL PARTS LIST

NO.	Sketch	Description of parts	Qty/pcs
1		Тор	1
2		Iron plate	1
3	9	Screw with M8*15	12
4	/	Wrench	1
5	9	Base	1