


If you are running extremely large shocks, bend along this line in a vice or similar.



Cut along this line

Cut along this line