Tesys to Everlink cross references

Old Tesys Reference	Everlink Equivalent
LRD3359A66	Supeseded by LRD3656
LRD3359	Supeseded by LRD365
LRD3357A66	Supeseded by LRD3506
LRD3357	Supeseded by LRD3500 Supeseded by LRD350
LRD3355A66	Supeseded by LRD3406
LRD3355A00	Supeseded by LRD3406 Supeseded by LRD340
LRD3353A66	Supeseded by LRD340 Supeseded by LRD3326
LRD3353A66	Supeseded by LRD3326 Supeseded by LRD332
LRD3322A66	
	Superseded by LRD3256
LRD3322 LRD3321A66	Supeseded by LRD325 Supeseded by LRD3186
LRD3321	Superseded by LRD318
LRD3316A66	Supeseded by LRD3136
LRD3316	Supeseded by LRD313
LR3D3359	Supeseded by LR3D365
LR3D3357	Supeseded by LR3D350
LR3D3355	Supeseded by LR3D340
LR3D3353	Supeseded by LR3D332
LR3D3322	Supeseded by LR3D325
LR2D3359S340	Supeseded by LRD365
LR2D3359S054	Supeseded by LRD365
LR2D3359A66	Supeseded by LRD3656
LR2D3359	Supeseded by LRD365
LR2D3357S340	Supeseded by LRD350
LR2D3357S054	Supeseded by LRD350
LR2D3357A66	Supeseded by LRD3506
LR2D3357	Supeseded by LRD350
LR2D3355S340	Supeseded by LRD340
LR2D3355S054	Supeseded by LRD340
LR2D3355A66	Supeseded by LRD3406
LR2D3355	Supeseded by LRD340
LR2D3353S340	Supeseded by LRD332
LR2D3353S103	Supeseded by LRD332
LR2D3353S054	Supeseded by LRD332
LR2D3353A66	Supeseded by LRD3326
LR2D3353	Supeseded by LRD332
LP1D65004UD	superseded by LC1DT80AUD
LP1D65004SW	superseded by LC1DT80ASD
LP1D65004SD	superseded by LC1DT80ASD
LP1D65004RD	superseded by LC1DT80ARD
LP1D65004ND	superseded by LC1DT80AND
LP1D65004MW	superseded by LC1DT80AMD
LP1D65004MD	superseded by LC1DT80AMD
LP1D65004JW	superseded by LC1DT80AJD
LP1D65004JD	superseded by LC1DT80AJD
LP1D65004GD	superseded by LC1DT80AGD
LP1D65004FW	superseded by LC1DT80AFD
LP1D65004FD	superseded by LC1DT80AFD
	1

LP1D65004EW	superseded by LC1DT80AED
LP1D65004ED	superseded by LC1DT80AED
LP1D65004CW	superseded by LC1DT80ACD
LP1D65004CD	superseded by LC1DT80ACD
LP1D65004BW	superseded by LC1DT80ABD
LP1D65004BD	superseded by LC1DT80ABD
LP1D650046SW	superseded by LC1DT80A6SD
LP1D40004UD	superseded by LC1DT60AUD
LP1D40004SW	superseded by LC1DT60ASD
LP1D40004SD	superseded by LC1DT60ASD
LP1D40004RD	superseded by LC1DT60ARD
LP1D40004ND	superseded by LC1DT60AND
LP1D40004MW	superseded by LC1DT60AMD
LP1D40004MD	superseded by LC1DT60AMD
LP1D40004JW	superseded by LC1DT60AJD
LP1D40004JD	superseded by LC1DT60AJD
LP1D40004GD	superseded by LC1DT60AGD
LP1D40004FW	superseded by LC1DT60AFD
LP1D40004FD	superseded by LC1DT60AFD
LP1D40004EW	superseded by LC1DT60AED
LP1D40004ED	superseded by LC1DT60AED
LP1D40004CW	superseded by LC1DT60ACD
LP1D40004CD	superseded by LC1DT60ACD
LP1D40004BW	superseded by LC1DT60ABD
LP1D40004BD	superseded by LC1DT60ABD
LP1D400046UD	superseded by LC1DT60A6UD
LP1D400046SW	superseded by LC1DT60A6BD
LP1D400046MW	superseded by LC1DT60A6MD
LP1D400046FW	superseded by LC1DT60A6FD
LP1D400046FD	superseded by LC1DT60A6FD
LP1D400046BW	superseded by LC1DT60A6BD
LP1D400046BD	superseded by LC1DT60A6BD
LC3D50V7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50V7	Superseded by Everlink offer - please talk to our technical department
LC3D50V5	Superseded by Everlink offer - please talk to our technical department
LC3D50U7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50U7	Superseded by Everlink offer - please talk to our technical department
LC3D50U5	Superseded by Everlink offer - please talk to our technical department
LC3D50T7	Superseded by Everlink offer - please talk to our technical department
LC3D50T6	Superseded by Everlink offer - please talk to our technical department
LC3D50S5	Superseded by Everlink offer - please talk to our technical department
LC3D50R7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50R7	Superseded by Everlink offer - please talk to our technical department
LC3D50R5	Superseded by Everlink offer - please talk to our technical department
LC3D50Q7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50Q7	Superseded by Everlink offer - please talk to our technical department
LC3D50Q5	Superseded by Everlink offer - please talk to our technical department
LC3D50P7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50P7	Superseded by Everlink offer - please talk to our technical department
LC3D50P5	Superseded by Everlink offer - please talk to our technical department
LC3D50N7A64	Superseded by Everlink offer - please talk to our technical department
LC3D50N7	Superseded by Everlink offer - please talk to our technical department

LC3D50N5 Superseded by Everlink offer - please talk to LC3D50M7A64 Superseded by Everlink offer - please talk to LC3D50M7 Superseded by Everlink offer - please talk to LC3D50M5 Superseded by Everlink offer - please talk to LC3D50K7 Superseded by Everlink offer - please talk to LC3D50FE7A64 Superseded by Everlink offer - please talk to LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department
LC3D50M7 Superseded by Everlink offer - please talk to LC3D50M5 Superseded by Everlink offer - please talk to LC3D50K7 Superseded by Everlink offer - please talk to LC3D50FE7A64 Superseded by Everlink offer - please talk to LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department
LC3D50M5 Superseded by Everlink offer - please talk to LC3D50K7 Superseded by Everlink offer - please talk to LC3D50FE7A64 Superseded by Everlink offer - please talk to LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department
LC3D50K7 Superseded by Everlink offer - please talk to LC3D50FE7A64 Superseded by Everlink offer - please talk to LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department our technical department our technical department our technical department
LC3D50FE7A64 Superseded by Everlink offer - please talk to LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department our technical department our technical department
LC3D50FE7 Superseded by Everlink offer - please talk to LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department our technical department
LC3D50F7A64 Superseded by Everlink offer - please talk to LC3D50F7 Superseded by Everlink offer - please talk to	our technical department
LC3D50F7 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
	our technical department
LCODEGEACA	our technical department
LC3D50F5A64 Superseded by Everlink offer - please talk to	our technical department
LC3D50F5 Superseded by Everlink offer - please talk to	our technical department
LC3D50E7A64 Superseded by Everlink offer - please talk to	our technical department
LC3D50E7 Superseded by Everlink offer - please talk to	our technical department
LC3D50E5 Superseded by Everlink offer - please talk to	our technical department
LC3D50D7A64 Superseded by Everlink offer - please talk to	our technical department
LC3D50D7 Superseded by Everlink offer - please talk to	our technical department
LC3D50D5 Superseded by Everlink offer - please talk to	our technical department
LC3D50B7A64 Superseded by Everlink offer - please talk to	·
LC3D50B7 Superseded by Everlink offer - please talk to	·
LC3D50B5 Superseded by Everlink offer - please talk to	
LC3D40V7A64 Superseded by Everlink offer - please talk to	
LC3D40V7 Superseded by Everlink offer - please talk to	
LC3D40U7A64 Superseded by Everlink offer - please talk to	
LC3D40U7 Superseded by Everlink offer - please talk to	
LC3D40U5 Superseded by Everlink offer - please talk to	
LC3D40R7A64 Superseded by Everlink offer - please talk to	
LC3D40R7 Superseded by Everlink offer - please talk to	
LC3D40R5 Superseded by Everlink offer - please talk to	
LC3D40Q7A64 Superseded by Everlink offer - please talk to	
LC3D40Q7 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
LC3D40Q5 Superseded by Everlink offer - please talk to	·
LC3D40P7A64 Superseded by Everlink offer - please talk to	·
LC3D40P7 Superseded by Everlink offer - please talk to	·
LC3D40F7 Superseded by Everlink offer - please talk to	·
LC3D40N7A64 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
LC3D40N7 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
	·
LC3D40N7	·
LC3D40M7A64 Superseded by Everlink offer - please talk to	·
LC3D40M7 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
LC3D40M5 Superseded by Everlink offer - please talk to	<u> </u>
LC3D40K7 Superseded by Everlink offer - please talk to	·
LC3D40FE7A64 Superseded by Everlink offer - please talk to	· · · · · · · · · · · · · · · · · · ·
LC3D40FE7 Superseded by Everlink offer - please talk to	·
LC3D40F7A64 Superseded by Everlink offer - please talk to	·
LC3D40F7 Superseded by Everlink offer - please talk to	·
LC3D40F5 Superseded by Everlink offer - please talk to	·
LC3D40E7A64 Superseded by Everlink offer - please talk to	·
LC3D40E7 Superseded by Everlink offer - please talk to	·
LC3D40E5 Superseded by Everlink offer - please talk to	·
LC3D40D7A64 Superseded by Everlink offer - please talk to	·
LC3D40D7 Superseded by Everlink offer - please talk to	<u> </u>
LC3D40D5 Superseded by Everlink offer - please talk to	our technical department

L COD 40D 7 4 C 4	Compared and how Experience officer in the page to the second to the provide a department of the second to the sec
LC3D40B7A64	Superseded by Everlink offer - please talk to our technical department
LC3D40B7	Superseded by Everlink offer - please talk to our technical department
LC3D40B5	Superseded by Everlink offer - please talk to our technical department
LC2D65W6	superseded by LC2D65AW7
LC2D65V7	superseded by LC2D65AV7
LC2D65V5	superseded by LC2D65AV7
LC2D65U7	superseded by LC2D65AU7
LC2D65U6	superseded by LC2D65AU7
LC2D65U5	superseded by LC2D65AU7
LC2D65T6	superseded by LC2D65AT7
LC2D65S5	superseded by LC2D65AS7
LC2D65R7	superseded by LC2D65AR7
LC2D65R6	superseded by LC2D65AR7
LC2D65R5	superseded by LC2D65AR7
LC2D65Q7	superseded by LC2D65AQ7
LC2D65Q6	superseded by LC2D65AQ7
LC2D65Q5	superseded by LC2D65AQ7
LC2D65P7	superseded by LC2D65AP7
LC2D65P5	superseded by LC2D65AP7
LC2D65N7	superseded by LC2D65AN7
LC2D65N6	superseded by LC2D65AN7
LC2D65N5	superseded by LC2D65AN7
LC2D65M7	superseded by LC2D65AM7
LC2D65M6	superseded by LC2D65AM7
LC2D65M5	superseded by LC2D65AM7
LC2D65LE7	superseded by LC2D65ALE7
LC2D65L7	superseded by LC2D65AL7
LC2D65K7	superseded by LC2D65AK7
LC2D65J5	superseded by LC2D65AJ5
LC2D65G7	superseded by LC2D65AG7
LC2D65G6	superseded by LC2D65AG7
LC2D65G5	superseded by LC2D65AG7
LC2D65FE7	superseded by LC2D65AFE7
LC2D65FE5	superseded by LC2D65AFE7
LC2D65F7	superseded by LC2D65AF7
LC2D65F6	superseded by LC2D65AF7
LC2D65F5	superseded by LC2D65AF7
LC2D65E7	superseded by LC2D65AE7
LC2D65E6	superseded by LC2D65AE7
LC2D65E5	superseded by LC2D65AE7
LC2D65D7	superseded by LC2D65AD7
LC2D65B7	superseded by LC2D65AB7
LC2D65B6	superseded by LC2D65AB7
LC2D65B5	superseded by LC2D65AB7
LC2D50W6	superseded by LC2D50AW7
LC2D50V7	superseded by LC2D50AV7
LC2D50V5	superseded by LC2D50AV7
LC2D50U7	superseded by LC2D50AU7
LC2D50U6	superseded by LC2D50AU7
LC2D50U5	superseded by LC2D50AU7
LC2D50T6	superseded by LC2D50AT7
LC2D50R7	superseded by LC2D50AR7

LC2D50R6	superseded by LC2D50AR7
LC2D50R5	superseded by LC2D50AR7
LC2D50Q7	superseded by LC2D50AQ7
LC2D50Q6	superseded by LC2D50AQ7
LC2D50Q5	superseded by LC2D50AQ7
LC2D50P7	superseded by LC2D50AP7
LC2D50P5	superseded by LC2D50AP7
LC2D50N7	superseded by LC2D50AN7
LC2D50N6	superseded by LC2D50AN7
LC2D50N5	superseded by LC2D50AN7
LC2D50M7	superseded by LC2D50AM7
LC2D50M6	superseded by LC2D50AM7
LC2D50M5	superseded by LC2D50AM7
LC2D50L7	superseded by LC2D50AL7
LC2D50K7	superseded by LC2D50AK7
LC2D50J5	superseded by LC2D50AJ5
LC2D50G7	superseded by LC2D50AG7
LC2D50G6	superseded by LC2D50AG7
LC2D50G5	superseded by LC2D50AG7
LC2D50FE7	superseded by LC2D50AFE7
LC2D50FE5	superseded by LC2D50AFE7
LC2D50F7	superseded by LC2D50AF7
LC2D50F6	superseded by LC2D50AF7
LC2D50F5	superseded by LC2D50AF7
LC2D50E7	superseded by LC2D50AE7
LC2D50E6	superseded by LC2D50AE7
LC2D50E5	superseded by LC2D50AE7
LC2D50D7	superseded by LC2D50AD7
LC2D50B7	superseded by LC2D50AB7
LC2D50B6	superseded by LC2D50AB7
LC2D50B5	superseded by LC2D50AB7
LC2D40V7	superseded by LC2D40AV7
LC2D40V5	superseded by LC2D40AV7
LC2D40U7	superseded by LC2D40AU7
LC2D40U6	superseded by LC2D40AU7
LC2D40U5	superseded by LC2D40AU7
LC2D40T6	superseded by LC2D40AT7
LC2D40R7	superseded by LC2D40AR7
LC2D40R6	superseded by LC2D40AR7
LC2D40R5	superseded by LC2D40AR7
LC2D40Q7	superseded by LC2D40AR7
LC2D40Q7	superseded by LC2D40AQ7
LC2D40Q5	superseded by LC2D40AQ7
LC2D40Q3	superseded by LC2D40AQ7 superseded by LC2D40AQ7
LC2D40P5	superseded by LC2D40AP7
LC2D40N7	superseded by LC2D40AP7 superseded by LC2D40AN7
LC2D40N7	superseded by LC2D40AN7
LC2D40N5	superseded by LC2D40AN7
LC2D40M7	superseded by LC2D40AM7
LC2D40M7	superseded by LC2D40AM7
LC2D40M5	superseded by LC2D40AM7
LC2D40N3	superseded by LC2D40Alvi7 superseded by LC2D40AL7
LUZUTULI	ouporoudou by LOZD TO ILI

LC2D40K7	superseded by LC2D40AK7
LC2D40J5	superseded by LC2D40AJ5
LC2D40G7	superseded by LC2D40AG7
LC2D40G6	superseded by LC2D40AG7
LC2D40G5	superseded by LC2D40AG7
LC2D40FE7	superseded by LC2D40AFE7
LC2D40FE5	superseded by LC2D40AFE7
LC2D40F7	superseded by LC2D40AF7
LC2D40F6	superseded by LC2D40AF7
LC2D40F5	superseded by LC2D40AF7
LC2D40E7	superseded by LC2D40AE7
LC2D40E6	superseded by LC2D40AE7
LC2D40E5	superseded by LC2D40AE7
LC2D40D7	superseded by LC2D40AD7
LC2D40D5	superseded by LC2D40AD7
LC2D40B7	superseded by LC2D40AB7
LC2D40B6	superseded by LC2D40AB7
LC2D40B5	superseded by LC2D40AB7
LC1D65Y5	superseded by LC1D65AYC7
LC1D65V7	superseded by LC1D65AV7
LC1D65UD	superseded by LC1D65AUD
LC1D65U7TQ	superseded by LC1D65AU7TQ
LC1D65U7	superseded by LC1D65AU7
LC1D65U6	superseded by LC1D65AU7
LC1D65U5	superseded by LC1D65AU7
LC1D6505 LC1D65SW	
	superseded by LC1D65ASD
LC1D65SD	superseded by LC1D65ASD
LC1D65S5	superseded by LC1D65AS7
LC1D65RD	superseded by LC1D65ARD
LC1D65R7	superseded by LC1D65AR7
LC1D65R6	superseded by LC1D65AR7
LC1D65Q7	superseded by LC1D65AQ7
LC1D65Q6	superseded by LC1D65AQ7
LC1D65P7	superseded by LC1D65AP7
LC1D65ND	superseded by LC1D65AND
LC1D65N7	superseded by LC1D65AN7
LC1D65N6	superseded by LC1D65AN7
LC1D65N5	superseded by LC1D65AN7
LC1D65MD	superseded by LC1D65AMD
LC1D65M7	superseded by LC1D65AM7
LC1D65LE7	superseded by LC1D65ALE7
LC1D65L6	superseded by LC1D65ALE7
LC1D65K7	superseded by LC1D65AK7
LC1D65JD	superseded by LC1D65AJD
LC1D65J5	superseded by LC1D65AJ5
LC1D65G6	superseded by LC1D65AG7
LC1D65FE7	superseded by LC1D65AFE7
LC1D65FE5	superseded by LC1D65AFE7
LC1D65FD	superseded by LC1D65AFD
LC1D65F7	superseded by LC1D65AF7
LC1D65F5	superseded by LC1D65AF7
LC1D65ED	superseded by LC1D65AED

LC1D65E7	superseded by LC1D65AE7
LC1D65E5	superseded by LC1D65AE7
LC1D65D5	superseded by LC1D65AD7
LC1D65CW	superseded by LC1D65ACD
LC1D65C5	superseded by LC1D65AC7
LC1D65BD	superseded by LC1D65ABD
LC1D65B7	superseded by LC1D65AB7
LC1D65B5	superseded by LC1D65AB7
LC1D656SW	superseded by LC1D65A6SD
LC1D656R7	superseded by LC1D65A6R7
LC1D656Q7	superseded by LC1D65A6Q7
LC1D656P7	superseded by LC1D65A6P7
LC1D656P5	superseded by LC1D65A6P7
LC1D656M7	superseded by LC1D65A6M7
LC1D656M6	superseded by LC1D65A6M7
LC1D656M5	superseded by LC1D65A6M7
LC1D656LE7	superseded by LC1D65A6LE7
LC1D656L7	superseded by LC1D65A6L7
LC1D656K7	superseded by LC1D65A6K7
LC1D656GD	superseded by LC1D65A6GD
LC1D656G7	superseded by LC1D65A6G7
LC1D656G6	superseded by LC1D65A6G7
LC1D656FW	superseded by LC1D65A6FD
LC1D656FE7	superseded by LC1D65A6FE7
LC1D656FD	superseded by LC1D65A6FD
LC1D656F7	superseded by LC1D65A6F7
LC1D656ED	superseded by LC1D65A6ED
LC1D656E7	superseded by LC1D65A6E7
LC1D656BW	superseded by LC1D65A6BD
LC1D656BD	superseded by LC1D65A6BD
LC1D656B7	superseded by LC1D65A6B7
LC1D656B5	superseded by LC1D65A6B7
LC1D65004U7	superseded by LC1DT80AU7
LC1D65004U5	superseded by LC1DT80AU7
LC1D65004R5	superseded by LC1DT80AR7
LC1D65004R5	superseded by LC1DT80AP7
LC1D65004P7	superseded by LC1DT80AP7 superseded by LC1DT80AP7
LC1D65004N7 LC1D65004M7	superseded by LC1DT80AN7
	superseded by LC1DT80AM7
LC1D65004FE7	superseded by LC1DT80AFE7
LC1D65004FE5	superseded by LC1DT80AFE7
LC1D65004F7	superseded by LC1DT80AF7
LC1D65004F5	superseded by LC1DT80AF7
LC1D65004E7	superseded by LC1DT80AB7
LC1D65004B7	superseded by LC1DT80AB7
LC1D65004B5	superseded by LC1DT80AB7
LC1D650046M7	superseded by LC1DT80A6M7
LC1D50Y5	superseded by LC1D50AYC7
LC1D50X6	superseded by LC1D50AX7
LC1D50W6	superseded by LC1D50AW7
LC1D50V7	superseded by LC1D50AV7
LC1D50U7	superseded by LC1D50AU7

LC1D50U5	superseded by LC1D50AU7
LC1D50T6	superseded by LC1D50AT7
LC1D50SW	superseded by LC1D50ASD
LC1D50S6	superseded by LC1D50ASC7
LC1D50RD	superseded by LC1D50ARD
LC1D50R7	superseded by LC1D50AR7
LC1D50Q7	superseded by LC1D50AQ7
LC1D50Q6	superseded by LC1D50AQ7
LC1D50P7	superseded by LC1D50AP7
LC1D50P5	superseded by LC1D50AP7
LC1D50ND	superseded by LC1D50AND
LC1D50N7	superseded by LC1D50AN7
LC1D50N6	superseded by LC1D50AN7
LC1D50MD	superseded by LC1D50AMD
LC1D50M7	superseded by LC1D50AM7
LC1D50M5	superseded by LC1D50AM7
LC1D50LE7	superseded by LC1D50ALE7
LC1D50L7	superseded by LC1D50AL7
LC1D50K7	superseded by LC1D50AK7
LC1D50JW	superseded by LC1D50AJD
LC1D50JD	superseded by LC1D50AJD
LC1D50J5	superseded by LC1D50AJ5
LC1D50GD	superseded by LC1D50AGD
LC1D50G7	superseded by LC1D50AG7
LC1D50G5	superseded by LC1D50AFC7
LC1D50FW	superseded by LC1D50AFD
LC1D50FE7	superseded by LC1D50AFE7
LC1D50FE5	superseded by LC1D50AFE7
LC1D50FD	superseded by LC1D50AFD
LC1D50FD	superseded by LC1D50AF7
LC1D50F7	superseded by LC1D50AF7 superseded by LC1D50AF7
LC1D50F6	superseded by LC1D50AF7 superseded by LC1D50AF7
LC1D50F5	superseded by LC1D50AF7 superseded by LC1D50AED
LC1D50ED	superseded by LC1D50AED superseded by LC1D50AE7
	· · · ·
LC1D50D7	superseded by LC1D50AD7
LC1D50D5	superseded by LC1D50AD7
LC1D50CW	superseded by LC1D50ACD
LC1D50BW	superseded by LC1D50ABD
LC1D50BD	superseded by LC1D50ABD
LC1D50B7	superseded by LC1D50AB7
LC1D50B5	superseded by LC1D50AB7
LC1D506U6	superseded by LC1D50A6U7
LC1D506SD	superseded by LC1D50A6SD
LC1D506R7	superseded by LC1D50A6R7
LC1D506Q7	superseded by LC1D50A6Q7
LC1D506P7	superseded by LC1D50A6P7
LC1D506P5	superseded by LC1D50A6P7
LC1D506M6	superseded by LC1D50A6M7
LC1D506L7	superseded by LC1D50A6L7
LC1D506JW	superseded by LC1D50A6JD
LC1D506GD	superseded by LC1D50A6GD
LC1D506G6	superseded by LC1D50A6G7

LC1D506G5	superseded by LC1D50A6G7
LC1D506FW	superseded by LC1D50A6FD
LC1D506FE7	superseded by LC1D50A6FE7
LC1D506FE5	superseded by LC1D50A6FE7
LC1D506FD	superseded by LC1D50A6FD
LC1D506F7	superseded by LC1D50A6F7
LC1D506EW	superseded by LC1D50A6ED
LC1D506ED	superseded by LC1D50A6ED
LC1D506E7	superseded by LC1D50A6E7
LC1D506D7	superseded by LC1D50A6D7
LC1D506CW	superseded by LC1D50A6CD
LC1D506CD	superseded by LC1D50A6CD
LC1D506BD	superseded by LC1D50A6BD
LC1D506B5	superseded by LC1D50A6B7
LC1D40W6	superseded by LC1D40AW7
LC1D40V7	superseded by LC1D40AV7
LC1D40V5	superseded by LC1D40AV7
LC1D40UD	superseded by LC1D40AUD
LC1D40U7	superseded by LC1D40AU7
LC1D40U5	superseded by LC1D40AU7
LC1D40T6	superseded by LC1D40AT7
LC1D40S6	superseded by LC1D40AS7
LC1D40R7	superseded by LC1D40AR7
LC1D40R7	superseded by LC1D40AR7 superseded by LC1D40AR7
LC1D40R3	
LC1D40Q7 LC1D40Q6	superseded by LC1D40AQ7
	superseded by LC1D40AQ7
LC1D40P7	superseded by LC1D40AP7
LC1D40N7	superseded by LC1D40AN7
LC1D40N6	superseded by LC1D40AN7
LC1D40N5	superseded by LC1D40AN7
LC1D40MD	superseded by LC1D40AMD
LC1D40M7	superseded by LC1D40AM7
LC1D40LE7	superseded by LC1D40ALE7
LC1D40L7	superseded by LC1D40AL7
LC1D40K7	superseded by LC1D40AK7
LC1D40JD	superseded by LC1D40AJD
LC1D40G7	superseded by LC1D40AG7
LC1D40FE7	superseded by LC1D40FE7
LC1D40FE5	superseded by LC1D40FE7
LC1D40FD	superseded by LC1D40AFD
LC1D40F7	superseded by LC1D40AF7
LC1D40F6	superseded by LC1D40AF7
LC1D40F5	superseded by LC1D40AF7
LC1D40ED	superseded by LC1D40AED
LC1D40E7	superseded by LC1D40AE7
LC1D40E5	superseded by LC1D40AE7
LC1D40D7	superseded by LC1D40AD7
LC1D40C5	superseded by LC1D40AC7
LC1D40BW	superseded by LC1D40ABD
LC1D40BD	superseded by LC1D40ABD
LC1D40B7TQ	superseded by LC1D40AB7TQ
LC1D40B7	superseded by LC1D40AB7

LC1D40B5	superseded by LC1D40AB7
LC1D406UD	superseded by LC1D40A6UD
LC1D406SW	superseded by LC1D40A6SD
LC1D406R7	superseded by LC1D40A6R7
LC1D406P7	superseded by LC1D40A6P7
LC1D406P5	superseded by LC1D40A6P7
LC1D406MW	superseded by LC1D40A6MD
LC1D406MD	superseded by LC1D40A6MD
LC1D406M7	superseded by LC1D40A6M7
LC1D406M6	superseded by LC1D40A6M7
LC1D406M5	superseded by LC1D40A6M7
LC1D406LE7	superseded by LC1D40A6LE7
LC1D406L7	superseded by LC1D40A6L7
LC1D406K7	superseded by LC1D40A6K7
LC1D406G7	superseded by LC1D40A6G7
LC1D406G6	superseded by LC1D40A6G7
LC1D406FW	superseded by LC1D40A6FD
LC1D406FE7	superseded by LC1D40A6FE7
LC1D406FD	superseded by LC1D40A6FD
LC1D406F7	superseded by LC1D40A6F7
LC1D406EW	superseded by LC1D40A6ED
LC1D406ED	superseded by LC1D40A6ED
LC1D406E7	superseded by LC1D40A6E7
LC1D406D5	superseded by LC1D40A6D7
LC1D406CW	superseded by LC1D40A6CD
LC1D406CD	superseded by LC1D40A6CD
LC1D406BW	superseded by LC1D40A6BD
LC1D406BD	
LC1D406BD	superseded by LC1D40A6B7 superseded by LC1D40A6B7
LC1D406B7	
LC1D406B5 LC1D40004U7	superseded by LC1D40A6B7
	superseded by LC1DT60AU7
LC1D40004U5	superseded by LC1DT60AD7
LC1D40004P7	superseded by LC1DT60AP7
LC1D40004N7	superseded by LC1DT60AN7
LC1D40004N5	superseded by LC1DT60AN7
LC1D40004M7	superseded by LC1DT60AM7
LC1D40004M5	superseded by LC1DT60AM7
LC1D40004FE5	superseded by LC1DT60AFE7
LC1D40004F7	superseded by LC1DT60AF7
LC1D40004F5	superseded by LC1DT60AF7
LC1D40004E7	superseded by LC1DT60AE7
LC1D40004E5	superseded by LC1DT60AE7
LC1D40004B7	superseded by LC1DT60AB7
LC1D40004B5	superseded by LC1DT60AB7
LC1D400046P7	superseded by LC1DT60A6P7
LC1D400046M5	superseded by LC1DT60A6M7
LC1D400046E7	superseded by LC1DT60A6E7
LC1D400046B7	superseded by LC1DT60A6B7
GV3ME63	superseded by GV3P50
GV3ME63	superseded by GV3P65
GV3ME40	superseded by GV3P32
GV3ME40	superseded by GV3P40

GV3ME25	superseded by GV3P25
GV3ME20	superseded by GV3P13
GV3ME20	superseded by GV3P18
GV3ME14	superseded by GV2P14
GV3ME10	superseded by GV2P10
GV3ME08	superseded by GV2P08
GV3ME07	superseded by GV2P07
GV3ME06	superseded by GV2P06
GK3EF65	superseded by GV3L50
GK3EF65	superseded by GV3L65
GK3EF40	superseded by GV3L25
GK3EF40	superseded by GV3L32
GK3EF40	superseded by GV3L40