

USC CROSS TALK ARTICLE INDEX

Link to Cross Talk Archives: <http://fccchr.usc.edu/crosstalk.html>

Winter 2016

-Vaults, Pits and Assemblies

Autumn 2015

-Preparing Assemblies for Freezing Temperatures

-Testing Detector Assemblies

Summer 2015

-Oversizing a Backflow Prevention Assembly

Spring 2015

-Undersizing Backflow Prevention Assemblies

Winter 2015

Lead-Free Assemblies Model Designations and the USC List

Autumn 2014

-The Usefulness of the No.1 Test Cock on a DC

Summer 2014

-Does a Failed Assembly Prevent Backflow?

Spring 2014

-Installation Guidelines

-Certification at Training Courses

Winter 2014

-Lead-free parts and Foundation Approval

Autumn 2013

-Gage Squirting

Summer 2013

-Are Hydrants a concern for Cross-Connections?

-About the RP Field Test

-Training Tools The Essentials

Winter 2013

-Direction of Flow

Autumn 2012

-Detector Assemblies and Pressure Loss

-Differences among Vacuum Breakers

Summer 2012

-Standard for Field Test Kits

-Manifold vs Parallel Assemblies

Winter/Spring 2012

-Hydraulic Lock

-Disc Compression

-Exercising the Relief Valve

-Testing the Double Check

-Location of Test Cock No.4 on Detector Assemblies

Autumn 2011

-Residential Fire Sprinkler Systems and Backflow Protection

-Winterizing and Shutoff Valves

Summer 2011

-Modifications and Foundation Approval

Spring 2011

-Exercising the Relief Valve

-Explaining the Relief Valve

Summer 2010

-The List: Shutoff Valves

-Water Meters: part of a detector assembly

Spring 2010

-Testing a Double Check Valve Assembly Vertically

Winter 2010

-Low-Head Drainage in Irrigation

Winter/Spring 2009

-Detector Assemblies

-Assemblies: Upside Down

Autumn 2008

-Winterizing Backflow Prevention Assemblies

-Field Testing the RP- Leaky #2 SOV

Summer 2008

-RP: Direction of Flow Test

-What is Disc Compression

Winter 2008

-Relief Valve Discharge

Summer 2007

-Orientation of Assemblies

Spring 2007

-Repairing an Approved Assembly

-Fire Hydrants and Cross-Connection Control

Summer 2006

-Direct vs Indirect Cross-Connections

-Properly Identify a Backflow Preventer

-Think Twice Before Rotating that NO. 2 Test Cock by Rotating the No.2 Shutoff Valve

Spring 2006

-Proper Installation AVB/PVB/SVB

Winter 2006

-Detector Assembly Spare Parts

Summer 2005

-Undersizing Backflow Preventers

-Aesthetics of Backflow Prevention Assemblies

-Double Checks on Irrigation Systems

Spring 2005

-Relief Valve Discharge Rates

-In the Field: Watts 2" 009M2QT RP

Winter 2005

-Flipping the Disc while Repairing Assemblies

-Thermal Expansion and Water Hammer

Autumn 2004

-Frozen Shut Off Valves

Spring 2004

-Field Modifications DC to a DCDA

Autumn 2003

-Exercising the Relief Valve

Winter 2003

-Approved Assemblies

-Cross-Connections in Household Plumbing

Spring 2001

-Testing the Double Check Valve Assembly

Summer 2000

-Direct vs. Indirect Cross-Connection

Summer 1999

-Disassembling Assemblies

Spring 1999

-Bleeding the Test Cocks

Spring 1998

-Troubleshooting: There's more to a Test than hooking up a gage

Winter 1998

-Protective Enclosure for Backflow Preventers

Autumn 1997

-Installing Double Checks Below Grade

Summer 1997

-What is Disc Compression?

Winter 1997

-Why Does the Relief Valve open?

-Flipping the Disc While Repairing Assemblies

October 1996

-Testing the RP

July 1996

- Testing a Vertical Double Check

- Testing the PVB

April 1996

-Why Does the Relief Valve Opening Point Change?

December 1995

-Testing the Double Check, Handling Disc Compression

-Applications of the SVB

February 1995

-Preparing for Recertification

November 1994

- Testing the Double Check, Backpressure Test vs. Direction of Flow Test

- Testing the Relief Valve, Does it open fully?

July 1994

- Testing the RP. An Optional Direction-of-Flow Test for the No.2 Check Valve

- Failing Assemblies, When an Assembly Fails the Field Test, Does Back-flow Occur?

February 1994

-Testing Double Detector Assemblies

April 1993

- Why the Difference AVB vs. PVB

- Detector Assemblies

January 1993

-Changing a DC to an RP in the Field

October 1992

- *Foundation Pressure Loss vs. Flow Rate Curves*
- *Pressure Loss Curves*

July 1992

- *The 3 psi Buffer*
- *Vertical Approval Process*
- *Tests Performed Between Annual Tests*

April 1992

- *Using the Right Backflow Preventer*
- *Modifying Assemblies*
- *The Essentials of Cross-Connection Control*

January 1992

- *"Hands-on" Testing*
- *Is the Assembly Approved Yet?*
- *The Approval Process*
- *Pressure Vacuum Breakers as System Protection in CA*

October 1991

- *Testing the PVB*
- *Your Cross-Connection Control Program*

January 1991

- *Relief Valve Discharge Rates*
- *"Approved" Gages*
- *Pressure Vacuum Breakers*
- *Repairing the Wilkins 575 RP*

October 1990

- *Parallel Installations*

November 1989

- *Confliction RP Test Procedures*
- *Recertification*

-What is a Resilient Seated Valve?

August 1989

-Frozen Shut Off Valves

-Has the Relief Valve Opened?

-Who's Testing Backflow Preventers?

March 1988

-Updated Methods for PVB Testing

-Air Gap?

July 1987

-Are You Certified?

-Is the Assembly Approved?

-Field Testing: The Pressure Vacuum Breaker

April 1987

-Resilient Seated Shut-Off Valves and Testcocks

-Field Testing: Disc Compression

July 1970 (Special Issue)

-How Are You Sure?

-Look Ahead

-Small vs Large

-Value Received

October 1970

-How Many in Your System?

-An Interesting Safeguard

April 1970

-Field Evaluation Changed

January 1970

-Another Cross Connection

July 1969

-New Approvals

February 1968

-Two New Units

-Navy Specs

August 1967

-The Slow Down