

### IOMBX parts list (in order of recommended assembly)

<b>Qty.</b>	<b>Symbol</b>	<b>Description</b>
2	-	4-40 x 1/4" long pan head machine screws (Digi-Key H142)
2	-	4-40 hex nuts (Digi-Key H216)
2	J1,J2	Jumpers, make from no. 22 insulated solid wire
19	R1-R19	2.2K $\Omega$ resistors [red-red-red]
15	H1-H15	24-pin straight headers (Mouser 538-26-48-1241)

Author's recommendations for suppliers given in parentheses above with part numbers where applicable. Equivalent parts may be substituted. Resistors are 1/4W, 5 percent and color codes are given in brackets.