



MOTO Diag



Data Management



Personal Center



Support



Settings



Upgrade





Favorites



All

For



For



Notice

1. In actual operation, we found that for some Apulia vehicles equipped with TFT LCD instruments, it is necessary to "turn off OBD fault display", otherwise some data streams are displayed incorrectly.
2. Connect the M002 power cable to the vehicle battery when using the M004 or N004 diagnostic connector, as shown in the following figure:



3. When part of the models enter the ENG diagnosis continuously, it will prompt a communication failure and the system cannot be entered. Please wait 2 minutes before entering. The specific models information is as follows:

	Make	vehicle model	Model Year	System	function me
1	APRILIA	Sport City 250	Scooter VBB (2006-)	ENG	Magneti Ma
2	APRILIA	Atlantic 250	Scooter SPH (2006-)	ENG	Magneti Ma
3	APRILIA	Arrecife 250	Scooter SPH (2006-)	ENG	Magneti Ma
4	APRILIA	Scarabeo 250	Scooter VRB (2006-)	ENG	Magneti Ma





1 fault codes P0611 and P1607 (Data Buffer)

2 Troubles in entering Diagnosis

Back





1 ENG

2 ABS

3 Instrument panel

4 Service system (Service Lamp Reset)

5 Suspensions

Tech
Bulletin

Back





1 A

2 C

3 D

4 E

5 L

Back





1 SL 1000 Falco

2 SL 750 Shiver

3 SL 900 Shiver

4 SR


5 SR MAX

Back





L = Left
R = Right




Diag
Socket

Diag
Connecto

Cancel





M002+M004/N004

Diag
Socket

Diag
Connecto

Cancel





1 Initialization ⓘ

2 Throttle Self-Learn ⓘ

3 Engine variant ⓘ

4 1 CO setting ⓘ

5 2 CO setting ⓘ

Back

