


✓ USE ALL THE FOAMS.

The VMI 3500 weighs 52 lbs when boxed. It's important to use all of the packing foams to protect the motor and the frame of the machine from shipping damage. Repack the machine in the original box with the outer **and** inner foams. Use the guide below to place the inner foams properly.

VMI 3500 REPACKING TIPS



✓ WRITE THE RMA NUMBER ON THE OUTSIDE OF THE BOX.

✓ SEND IT BACK TO VENMILL.

Ship the machine back to VenMill Industries, 36 Town Forest Road, Oxford, MA 01540.

✓ DO THE HOKEY POKEY AND TURN YOURSELF ABOUT.

You just repacked and shipped your VMI 3500 like a pro. Boom.



Don't ship the machine without the proper box and foams. If you need packing foams, check the box on the RMA form or contact VenMill (866-864-0210).



Don't remove the buffing wheels. It's important to leave the buffing wheels installed on the machine for shipping, and so that the technician can properly test your machine.



Don't include any notes, forms, or paperwork in the box. If you have any additional information or specific instructions, email your technical support agent.