Quantum

NH72A SKELETON AUTOMATIC 3 HANDS



SETTING THE TIME

- 1) Unscrew & pull out the crown to the first click position.
- 2) Turn the crown clockwise to set the correct time.
- 3) Push the crown back into normal crown position.

Important

-ALWAYS ensure that the crown is securly screwed back to the case to ensure water resistance.

TO WIND UP THE MAINSPRING

- Manual winding > First unscrew the crown and turn the crown clockwise at normal position.
 Fully wound up by turning the crown minimum 55 times and give the watch a soft shake.
- To wind up with winding machine.

 Full wind up conditions
 - . Rotary speed: 30 rpm
 - . Operating time: 60 minutes
- * This watch MUST be worn for at least 8 (Eight) hours each day to ensure it is fully wound. An automatic watch will only wind when the watch is on your wrist and your arm moves. Winding the watch by the crown will put power on the spring but not enough to allow the watch to function fully. If your watch stops overnight or loses time it means it is not being fully wound.

