


EPMSM01 INSTRUCTIONS



TO REFILL MILL

UNSCREW TOP CASING (C) FROM THE GLASS BASE (A) BY TURNING COUNTER CLOCKWISE. POUR DESIRED SPICE (B) INTO THE GLASS BASE (A). FOR SMOOTH FUNCTIONING, NEVER FILL THE BASE (A) MORE THAN 90%. SECURELY FASTEN THE TOP CASING (C) BACK TO THE BASE (A) BY SCREWING ON CLOCKWISE

TO CARE

WIPE THE OUTSIDE OF THE MILL WITH A SOFT, DAMP CLOTH. NEVER IMMERSE YOUR MILL IN WATER. STORE YOUR MILL IN A DRY PLACE.

CAUTION

KEEP FINGERS CLEAR WHEN ATTACHING COVER.

- A. Glass Base
- B. Spice
- C. Top Casing