




Sleeve Nut should be installed last to connect shock to camber plate.

FD-CP-02/FB-CP-02
8th & 9th Gen V2 Camber Plate



ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	TP8-02L, TP8-02R, TP9-02	Camber Top Plate	2
2	SN-02	Sleeve Nut	2
3	TH-02	Top Hat	2
4	PB-02	Pillow Block	2
5	COM-12T	Spherical Bearing	2
6	M10x25mm Bolt	Flat Socket Head Bolt	6
7	M6x12mm Bolt	Socket Head Bolt	8
8	M6 Washer	Flat Washer	8
9	1 7/16 Snap Ring	Snap Ring	2
10	M10 Nut	M10 Nut	6

PROPRIETARY AND CONFIDENTIAL

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF **A-Spec Racing**. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF **A-Spec Racing** IS PROHIBITED.

A-Spec Racing Co. Chasworth CA
www.asrparts.com

MADE IN USA

Camber Plate V2