

DEBRIS REMOVAL SWABS



AVAILABLE IN

- 5-Pack - p/n F1-51005
- 100-Pack - p/n F1-5100100

The Debris Removal Swabs are designed to reach into tight spaces to allow you to clean dirt and debris from your fiber optic equipment. The Debris Removal Swabs are perfect for collecting fiber stubs out of your fiber cleavers and fusion splice machines. Simply remove the protective paper covering to expose the sticky tape underneath. Dirt and debris clings directly to the swab and allows safe disposal.

Warning: The Debris Removal Swab is not recommended for cleaning Cleaver blades or fusion splice electrodes.

SPECIFICATIONS

Length	6 inches
Width	1/4 inches
Material	Wood Handle with Adhesive Foam