

1 Minute Contact Time

1 STEP No gross debris present

2 STEP* Gross debris present

*Clean Before Disinfecting

**Low Alcohol Quaternary
Disinfectant Wipe**



Best Practices to Remove Surface Residues

- Choose appropriate products. Select for contact time, kill claims, aesthetics, and medical device manufacturers instructions for use.
- Examine equipment surfaces. Check for cracking, staining, discoloration, or any other early signs of residue issues.
- Follow wipe down procedures. Disinfectant manufacturers, Infection Preventionists, and equipment manufacturers recommend cleaning equipment surfaces after reaching the required contact time with a damp cloth or paper towel daily or weekly to remove disinfectant residues and help prevent potential staining, drying and cracking of equipment. Frequency procedure can be optimized based on your facility conditions.