

TPX™

12V USB POWER SUPPLY

- Disconnect the battery from motorcycle.
- Connect the Blue T-tap to a +12V switched wire on the motorcycle.
- Crimp the Red Terminal to the red wire on the unit.
- Connect the Red Terminal to the Blue T-tap.
- Crimp the Ring Terminal to the black wire on the unit (optional).
- Connect the black wire on the unit to ground or the negative terminal on the battery.
- Reconnect the battery to the motorcycle.

ADAPTIV™
TECHNOLOGIES

www.AdaptivTech.com

646-722-0253

866-ADAPTIV

4029-00 R1